





序号	报告编号	发布日期	结论	影像资料
1	GX-B1416/22-6-23011	2023/11/1	综合判定合格	 <p>2023 08 12</p>
2	GX-B1416/22-6-23012	2023/11/1	综合判定合格	 <p>2023 08 12</p>


3	GX-B1416/22-6-23013	2023/11/1	综合判定合格	
4	GX-B1416/22-6-23014	2023/11/1	综合判定合格	
5	GX-B1416/22-6-23015	2023/11/1	综合判定合格	

6	GX-B1416/22-6-23016	2023/11/1	综合判定合格	 <p>2023 08 13</p>
7	GX-B1416/22-6-23017	2023/11/1	综合判定合格	 <p>2023 08 13</p>
8	GX-B1304/21-6-23030	2023/11/1	综合判定合格	 <p>2023 10 15</p>

9	GX-B1428/21-6-23031	2023/11/2	无缺陷迹痕显示		
10	GX-B1428/21-6-23032	2023/11/2	无缺陷迹痕显示		
11	GX-B1352/21-6-23461~23464	2023/11/2	所检项目合格		

12	GX-B1352/21-6-23465	2023/11/2	所检项目合格	
13	GX-B1598/21-6-23049	2023/11/3	<p>实测钢丝绳有效截面积损失百分比最大为1.16%，小于5%为正常。</p>	
14	GX-B1598/21-6-23050	2023/11/3	<p>实测钢丝绳有效截面积损失百分比最大为1.28%，小于5%为正常。</p>	

15	GX-B1598/21-6-23051	2023/11/3	<p>实测钢丝绳有效截面积损失百分比最大为1.43%，小于5%为正常。</p>	
16	GX-B1598/21-6-23052	2023/11/3	<p>实测钢丝绳有效截面积损失百分比最大为1.20%，小于5%为正常。</p>	
17	GX-B1598/21-6-23053	2023/11/3	<p>实测钢丝绳有效截面积损失百分比最大为4.84%，小于5%为正常。</p>	

18	GX-B1598/21-6-23054	2023/11/3	实测钢丝绳有效截面积损失百分比最大为4.85%，小于5%为正常。		 A photograph showing a worker in a blue uniform and red helmet standing next to a yellow safety railing in an industrial setting. The worker is looking towards the camera. The background shows some industrial equipment and a tunnel-like structure. A date stamp '2023-10-11' is visible in the bottom right corner of the photo.	
----	---------------------	-----------	----------------------------------	--	---	--