

序号	报告编号	发布日期	结论	影像资料
3	GX-B1340/23-9-24049	2024. 8. 9	2#在用主要通风机系统合格。	
4	GX-B1340/23-9-24050	2024. 8. 9	1#在用主要通风机系统合格。	
5	GX-B1340/23-9-24045	2024. 8. 9	北风井1#在用主要通风机系统合格。	

6	GX-B1340/23-9-24046	2024. 8. 9	北风井2#在用主要通风机系统合格。	 A photograph showing two men in safety gear standing next to a large blue industrial fan unit. One man is wearing a black t-shirt with a star logo and a black cap, while the other is wearing an orange jumpsuit and a red hard hat. The fan unit has a '2' on it. A timestamp '2024.06.15' is visible in the bottom right corner of the photo.
7	GX-B1340/23-9-24054	2024年8月13日	1#主要通风机系统合格。	 A photograph showing three men in safety gear standing in a room with blue checkered flooring. They are wearing blue shirts and red hard hats. A red circle with the number '1' is visible in the background.
8	GX-B1340/23-9-24055	2024年8月13日	2#主要通风机系统合格。	 A photograph showing three men in safety gear standing in a room with blue checkered flooring. They are wearing blue shirts and red hard hats. A red circle with the number '2' is visible in the background.

9	GX-B1341/24-9-24170	2024.8.13	综合判定：合格。		
10	GX-B1341/24-9-24171	2024.8.13	综合判定：合格。		
11	GX-B1341/24-9-24172	2024.8.13	综合判定：合格。		

12	GX-B1343/21-9-24039	2024.8.13	<p>1. 矿井总进风量：2984.4m³/min，矿井总回风量：3001.5m³/min；</p> <p>2. 矿井有效风量：2019.7m³/min；</p> <p>3. 主通风机风量：3095.4m³/min，其中460西回风平窿通风机597.3m³/min，III矿体460平窿通风机696.7m³/min，+410m回风井口通风机1801.4m³/min；</p> <p>4. 矿井有效风量率：65.2%；</p> <p>5. 通风机负压：460西回风平窿通风机负压278Pa，III矿体460平窿通风机负压348Pa，+410m回风井口通风机负压698Pa；</p> <p>6. 矿井通风阻力：460西回风平窿通风系统267.0Pa，III矿体460平窿通风系统336.6Pa，+410m回风井口通风系统679.3Pa。</p>	
13	GX-B1347/21-9-24031	2024.8.13	<p>1、风量（风速）合格率：100%，大于65%，合格；</p> <p>2、风质合格率：100%，大于90%，合格；</p> <p>3、作业环境空气质量合格率：100%，大于60%，合格；</p> <p>4、矿井有效风量率：65.2%，大于60%，合格；</p> <p>5、风机全压效率：71.8%，大于70%，合格；</p> <p>6、风量供需比：1.43，符合$1.32 \leq \beta \leq 1.67$要求，合格；</p> <p>7、综合指标：88.1%，大于72%，合格。</p>	
14	GX-B1343/21-9-24041	2024.8.12	<p>1. 矿井总风量：28892.8m³/min；</p> <p>2. 主通风机风量：29291.5m³/min；其中北风井通风机风量8961.7m³/min，东南风井通风机风量9028.1m³/min，南风井通风机风量6647.8m³/min，港里1#回风井通风机风量4653.9m³/min；</p> <p>3. 矿井有效风量：17959.2m³/min；</p> <p>4. 矿井有效风量率：61.3%；</p> <p>5. 通风机负压：北风井通风机2053Pa，东南风井通风机1892Pa，南风井通风机1209Pa，港里1#回风井通风机910Pa；</p> <p>6. 矿井通风阻力：北风井通风系统2043.0Pa，东南风井通风系统1856.9Pa，南风井通风系统1187.3Pa，港里1#回风井通风系统895.2Pa。</p>	

15	GX-B1347/21-9-24032	2024.8.12	<p>1、风量（风速）合格率：100%，大于65%，合格； 2、风质合格率：100%，大于90%，合格； 3、作业环境空气质量合格率：100%，大于60%，合格； 4、矿井有效风量率：61.3%，大于60%，合格； 5、风机全压效率：74.7%，大于70%，合格； 6、风量供需比：1.50，符合$1.32 \leq \beta \leq 1.67$要求，合格； 7、综合指标：87.8%，大于72%，合格。</p>	 <p>2024-07-26</p>
16	GX-B1343/21-9-24042	2024.8.16	<p>1. 矿井总进风量：33.30 m³/s；矿井总回风量：37.65 m³/s； 2. 主通风机风量：38.27 m³/s； 3. 矿井有效风量：32.40 m³/s； 4. 矿井有效风量率：84.7%； 5. 主通风机负压：1013 Pa； 6. 矿井通风阻力：863.0 Pa。</p>	 <p>2024.07.05</p>
17	GX-B1341/24-9-24173	2024.8.14	综合判定：合格。	 <p>2024-07-13</p>

18	GX-B1343/21-9-24040	2024.8.14	<ol style="list-style-type: none">1. 矿井总进风量: 1254.6m³/min, 矿井总回风量: 1548.1m³/min;2. 矿井有效风量: 964.1m³/min;3. 主通风机风量: 1583.4m³/min;4. 矿井有效风量率: 60.9%;5. 通风机负压: 655m回风平硐主通风机338Pa;6. 矿井通风阻力: 318.7Pa。	
----	---------------------	-----------	---	---