

序号	报告编号	发布日期	结论	影像资料
1	GX-B1495/20-C-22279~22289	2022/6/1	所检项目合格	
2	GX-B1312/20-C-22107~22110	2022/6/1	所检项目合格	

2	GX-B1312/20-C-22111~22112	2022/6/1	所检项目合格	 A photograph showing two workers wearing red hard hats and safety gear. They are standing in a control room or equipment room, looking at a piece of equipment. A yellow timestamp '2022/4/17' is visible in the bottom right corner of the image.
3	GX-B1321/20-C-22118~22123	2022/6/1	所检项目合格	 A photograph showing two workers wearing red hard hats and safety gear. They are sitting on the floor in a control room or equipment room, working on equipment. A yellow timestamp '2022/4/17' is visible in the bottom right corner of the image.
4	GX-B1321/20-C-22124~22125	2022/6/1	所检项目合格	 A photograph showing a worker wearing a red hard hat and safety gear. The worker is sitting on the floor in a control room or equipment room, working on equipment. A yellow timestamp '2022/5/5' is visible in the bottom right corner of the image.