

序号	报告编号	发布日期	结论	影像资料
139	GX-B1363/22-A-22486	2022/12/14	所检项目合格	 A photograph showing two men in work clothes inspecting a large, complex industrial machine. The machine has a prominent vertical pipe on top and several panels. One man in a blue jacket is looking into an open panel, while the other in a grey jacket stands nearby. A green trash bin is visible on the left. The date '2022/12/09' is printed in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
140	GX-B1363/22-A-22480	2022/12/14	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
141	GX-B1363/22-A-22475	2022/12/14	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
142	GX-B1363/22-A-22485	2022/12/14	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
143	GX-B1363/22-A-22483	2022/12/15	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
144	GX-B1363/22-A-22484	2022/12/15	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
145	GX-B1363/22-A-22481	2022/12/15	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
146	GX-B1363/22-A-22482	2022/12/15	所检项目合格	



序号	报告编号	发布日期	结论	影像资料
147	GX-B1364/22-A-22958	2022/12/15	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
148	GX-B1364/22-A-22959	2022/12/15	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
149	GX-B1364/22-A-22960	2022/12/15	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
150	GX-B1364/22-A-22961	2022/12/15	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
151	GX-B1364/22-A-22962	2022/12/15	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
152	GX-B1365/20-A-22110	2022/12/15	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
153	GX-B1366/20-A-22143	2022/12/15	所检项目合格	