

序号	报告编号	发布日期	结论	影像资料
791	GX-B1306/21-Y-22029	2022年5月14日	合格	 A photograph of a control panel mounted on a green-painted metal surface. The panel features several analog gauges and indicators. At the top, there are two digital displays labeled 'rpm' and 'Mpa'. Below these are several red indicator lights and two rotary switches. At the bottom, there are two large analog pressure gauges and a smaller gauge. A yellow date stamp '2022.4.27' is visible in the bottom left corner of the image.
792	GX-B1306/21-Y-22030	2022年5月14日	合格	 A photograph of a control panel mounted on a grey metal surface. The panel has a central digital display screen. Below the screen are several buttons, including a red emergency stop button and a green start button. To the right of the panel is a red circular cap. A yellow date stamp '2022.4.27' is visible in the bottom left corner of the image.

793	GX-B1306/21-Y-22031	2022年5月14日	合格	 A photograph of a control panel mounted on a wall. The panel is dark grey or black and features a digital display screen at the top. Below the screen are several buttons, some of which are labeled with numbers. To the right of the buttons is a red emergency stop button. A yellow date stamp '2022.4.27' is visible in the bottom left corner of the image.
794	GX-B1306/21-Y-22032	2022年5月14日	合格	 A photograph showing industrial machinery and pipes. The scene is somewhat cluttered, with various metal components, pipes, and what appears to be a large cylindrical tank or container in the background. A yellow date stamp '2022.4.27' is visible in the bottom left corner of the image.

795	GX-B1306/21-Y-22033	2022年5月14日	合格	
796	GX-B1306/21-Y-22034	2022年5月14日	合格	

797	GX-B1306/21-Y-22035	2022年5月14日	合格	
798	GX-B1306/21-Y-22036	2022年5月14日	合格	

799	GX-B1306/21-Y-22037	2022年5月14日	合格	 A photograph showing the interior of an electrical control panel. It features a digital display screen with several indicator lights (red and green) and a row of buttons below it. The panel is mounted on a metal surface. A yellow date stamp '2022.4.27' is visible in the bottom left corner of the image.
800	GX-B1306/21-Y-22038	2022年5月14日	合格	 A close-up photograph of a mechanical component, likely a valve or sensor. It has a cylindrical shape with a threaded top section and a metal band wrapped around its middle. The component is mounted on a metal structure. A yellow date stamp '2022.4.27' is visible in the bottom left corner of the image.

801	GX-B1306/21-Y-22039	2022年5月14日	合格	
802	GX-B1306/21-Y-22040	2022年5月14日	合格	

803	GX-B1306/21-Y-22041	2022年5月14日	合格	 <p>A photograph of a blue control panel mounted in a metal enclosure. The panel features three digital displays at the top, labeled 'rpm', 'Mpa', and 'C'. Below the displays are several indicator lights and control knobs. A yellow date stamp '2022.4.27' is visible in the bottom left corner of the photo.</p>
804	GX-B1306/21-Y-22042	2022年5月14日	合格	 <p>A photograph of a grey control panel mounted in a metal enclosure. The panel features two analog gauges at the bottom, labeled 'Mpa' and 'Mpa'. Above the gauges are several indicator lights and control knobs. A yellow date stamp '2022.4.27' is visible in the bottom left corner of the photo.</p>

805	GX-B1306/21-Y-22043	2022年5月14日	合格	
806	GX-B1306/21-Y-22044	2022年5月14日	合格	

807	GX-B1522/20-Y-22029	2022年5月14日	合格	
808	GX-B1522/20-Y-22030	2022年5月14日	合格	

809	GX-B1522/20-Y-22031	2022年5月14日	合格	
810	GX-B1522/20-Y-22032	2022年5月14日	合格	

811	GX-B1522/20-Y-22033	2022年5月14日	合格	
812	GX-B1522/20-Y-22034	2022年5月14日	合格	

813	GX-B1522/20-Y-22035	2022年5月14日	合格	
814	GX-B1522/20-Y-22036	2022年5月14日	合格	

815	GX-B1522/20-Y-22037	2022年5月14日	合格	
816	GX-B1522/20-Y-22038	2022年5月14日	合格	

817	GX-B1522/20-Y-22039	2022年5月14日	合格	
818	GX-B1522/20-Y-22040	2022年5月14日	合格	

819	GX-B1522/20-Y-22041	2022年5月14日	合格	
820	GX-B1521/20-Y-22138	2022年5月14日	合格	

821	GX-B1521/20-Y-22139	2022年5月14日	合格	
822	GX-B1521/20-Y-22140	2022年5月14日	合格	

823	GX-B1521/20-Y-22141	2022年5月14日	合格	
824	GX-B1521/20-Y-22142	2022年5月14日	合格	

825	GX-B1521/20-Y-22143	2022年5月14日	合格	 A yellow excavator is shown working on a steep, rocky slope. The excavator's arm is extended, and it appears to be in the process of digging or moving material. The background shows a clear blue sky with some clouds. A yellow timestamp "2022/4/25" is visible in the bottom right corner of the image.
826	GX-B1521/20-Y-22144	2022年5月14日	合格	 A yellow excavator is shown loading a blue and white truck at a quarry. The excavator's bucket is raised, dumping material into the truck's bed. A person in a grey uniform and red hard hat is standing near the truck. The background shows a large, layered rock face. A yellow timestamp "2022/4/25" is visible in the bottom right corner of the image.

827	GX-B1521/20-Y-22120	2022年5月13日	合格	
828	GX-B1521/20-Y-22121	2022年5月14日	合格	

829	GX-B1521/20-Y-22122	2022年5月14日	合格	 A yellow Komatsu excavator is shown in operation on a construction site. The machine is positioned on a pile of dark, rocky material. The background features a hazy, mountainous landscape under a cloudy sky. A yellow timestamp "2022/4/23" is visible in the bottom right corner of the image.
830	GX-B1521/20-Y-22123	2022年5月13日	合格	 A yellow Volvo excavator is shown in operation on a construction site. The machine is positioned on a dirt and rock surface. The background features a hazy, mountainous landscape under a cloudy sky. A yellow timestamp "2022/4/24" is visible in the bottom right corner of the image.

831	GX-B1521/20-Y-22124	2022年5月13日	合格	 A yellow Liebherr excavator is shown in a quarry setting. The excavator is positioned on a dark, rocky surface. In the background, there are more excavators and a clear blue sky with scattered white clouds. A yellow timestamp '2022/4/24' is visible in the bottom right corner of the image.
832	GX-B1521/20-Y-22125	2022年5月13日	合格	 An orange excavator is shown in a quarry setting. The excavator is positioned on a dark, rocky surface. In the background, there are large rock formations and a cloudy sky. A yellow timestamp '2022/4/24' is visible in the bottom right corner of the image.

833	GX-B1521/20-Y-22126	2022年5月13日	合格	
834	GX-B1539/20-Y-22077	2022年5月14日	合格	

835	GX-B1539/20-Y-22078	2022年5月14日	合格	
836	GX-B1539/20-Y-22079	2022年5月14日	合格	

837	GX-B1539/20-Y-22080	2022年5月14日	合格	
838	GX-B1539/20-Y-22081	2022年5月14日	合格	

839	GX-B1539/20-Y-22082	2022年5月14日	合格	
840	GX-B1539/20-Y-22068	2022年5月14日	合格	

841	GX-B1539/20-Y-22069	2022年5月14日	合格	
842	GX-B1539/20-Y-22070	2022年5月14日	合格	

843	GX-B1539/20-Y-22071	2022年5月14日	合格	
844	GX-B1539/20-Y-22072	2022年5月14日	合格	

845	GX-B1539/20-Y-22073	2022年5月14日	合格	
846	GX-B1539/20-Y-22074	2022年5月14日	合格	

847	GX-B1557/21-Y-22002	2022年5月17日	合格	 <p>A yellow XCMG wheel loader is shown in a construction or mining site. A worker in a grey uniform and red hard hat stands next to the machine. The loader has 'XCMG' written on its side. A date stamp '2022/4/28' is visible in the bottom right corner of the photo.</p>
848	GX-B1423/20-Y-222156	2022年5月17日	合格	 <p>A large grey dump truck is shown in a construction or mining site. Two workers in grey uniforms and hard hats stand in front of the truck. A date stamp '2022/4/5' is visible in the bottom right corner of the photo.</p>

849	GX-B1423/20-Y-222157	2022年5月17日	合格	
850	GX-B1423/20-Y-222158	2022年5月17日	合格	

851	GX-B1423/20-Y-222159	2022年5月17日	合格	
852	GX-B1423/20-Y-222160	2022年5月17日	合格	

853	GX-B1423/20-Y-222161	2022年5月17日	合格	
854	GX-B1423/20-Y-222162	2022年5月17日	合格	

855	GX-B1423/20-Y-222163	2022年5月17日	合格	
856	GX-B1423/20-Y-222164	2022年5月17日	合格	

857	GX-B1423/20-Y-222165	2022年5月17日	合格	
858	GX-B1423/20-Y-222166	2022年5月17日	合格	

859	GX-B1423/20-Y-222167	2022年5月17日	合格	
860	GX-B1423/20-Y-222168	2022年5月17日	合格	

861	GX-B1423/20-Y-222169	2022年5月17日	合格	
862	GX-B1423/20-Y-222170	2022年5月17日	合格	

863	GX-B1423/20-Y-222171	2022年5月17日	合格	
864	GX-B1423/20-Y-222172	2022年5月17日	合格	

865	GX-B1423/20-Y-222173	2022年5月17日	合格	
866	GX-B1423/20-Y-222174	2022年5月17日	合格	

867	GX-B1423/20-Y-222175	2022年5月17日	合格	
868	GX-B1423/20-Y-222176	2022年5月17日	合格	

869	GX-B1423/20-Y-222177	2022年5月17日	合格	
870	GX-B1423/20-Y-222178	2022年5月17日	合格	

871	GX-B1423/20-Y-222179	2022年5月17日	合格	
872	GX-B1423/20-Y-222180	2022年5月17日	合格	

873	GX-B1423/20-Y-222181	2022年5月17日	合格	
874	GX-B1423/20-Y-222182	2022年5月17日	合格	

875	GX-B1423/20-Y-222183	2022年5月17日	合格	
876	GX-B1423/20-Y-222184	2022年5月17日	合格	

877	GX-B1423/20-Y-222185	2022年5月17日	合格	 <p>A yellow dump truck is parked on a dirt surface. Two workers wearing red hard hats and safety vests are standing in front of the truck. The truck has '0001' written on its side. A yellow timestamp '2022/4/6' is visible in the bottom right corner of the photo.</p>
878	GX-B1423/20-Y-222186	2022年5月17日	合格	 <p>A worker in a grey uniform and red helmet is standing next to a yellow dump truck. The worker is holding a device, possibly a camera or a tablet. The truck is parked on a dirt road. A yellow timestamp '2022/4/6' is visible in the bottom right corner of the photo.</p>

879	GX-B1423/20-Y-222187	2022年5月17日	合格	
880	GX-B1423/20-Y-222188	2022年5月17日	合格	

881	GX-B1423/20-Y-222189	2022年5月17日	合格	
882	GX-B1423/20-Y-222190	2022年5月17日	合格	

883	GX-B1423/20-Y-222191	2022年5月17日	合格	
884	GX-B1521/20-Y-22147	2022年5月17日	合格	

885	GX-B1521/20-Y-22148	2022年5月17日	合格	 A yellow excavator is shown in a quarry or construction site. The excavator is positioned on a dirt surface, and its arm is extended. The background shows a large, open-pit mine or quarry with a clear blue sky. A yellow timestamp "2022/4/6" is visible in the bottom right corner of the image.
886	GX-B1521/20-Y-22149	2022年5月17日	合格	 A worker wearing a red hard hat and a white uniform is seated in the operator's cab of a piece of heavy machinery. The worker is looking down at something in their hands. The interior of the cab is visible, showing various controls and levers. A yellow timestamp "2022/4/6" is visible in the bottom right corner of the image.

887	GX-B1521/20-Y-22150	2022年5月17日	合格	 A yellow excavator is shown in operation on a rocky, uneven terrain. The excavator's arm is extended, and its bucket is positioned near the ground. In the background, there is a large, light-colored hillside under a clear blue sky. A yellow timestamp '2022/4/6' is visible in the bottom right corner of the photo.
888	GX-B1521/20-Y-22151	2022年5月17日	合格	 A yellow excavator is shown loading material into the bed of a truck. The excavator's arm is raised, and its bucket is positioned over the truck's bed. The scene is set on a rocky slope with a large, light-colored hillside in the background under a clear blue sky. A yellow timestamp '2022/4/6' is visible in the bottom right corner of the photo.

889	GX-B1521/20-Y-22152	2022年5月17日	合格	 <p>A yellow excavator is shown in operation on a construction site. The excavator is positioned on a dirt surface, and its arm is extended. In the background, there is a large, steep pile of earth or rock. The sky is clear and blue. A yellow timestamp '2022/4/6' is visible in the bottom right corner of the image.</p>
890	GX-B1521/20-Y-22153	2022年5月17日	合格	 <p>A yellow excavator is shown loading a yellow dump truck with material. The excavator is positioned on a dirt surface, and its arm is extended towards the truck's bed. The truck is also on a dirt surface. In the background, there is a large, steep pile of earth or rock. The sky is clear and blue. A yellow timestamp '2022/4/6' is visible in the bottom right corner of the image.</p>

891	GX-B1521/20-Y-22154	2022年5月17日	合格	
892	GX-B1521/20-Y-22155	2022年5月17日	合格	

893	GX-B1521/20-Y-22156	2022年5月18日	合格	
894	GX-B1521/20-Y-22157	2022年5月18日	合格	

895	GX-B1539/20-Y-22084	2022年5月17日	合格	
896	GX-B1539/20-Y-22085	2022年5月17日	合格	

897	GX-B1539/20-Y-22086	2022年5月17日	合格	 <p>A yellow Komatsu wheel loader is parked inside a tunnel. Two workers in safety gear are standing next to it. The tunnel has a ribbed ceiling. A yellow timestamp '2022/4/6' is visible in the bottom right corner of the photo.</p>
898	GX-B1539/20-Y-22087	2022年5月17日	合格	 <p>A yellow wheel loader is parked inside a tunnel. Two workers in safety gear are standing next to it. The tunnel walls are visible. A yellow timestamp '2022/4/6' is visible in the bottom right corner of the photo.</p>

899	GX-B1557/21-Y-22004	2022年5月18日	合格	
900	GX-B1557/21-Y-22003	2022年5月17日	合格	

901	GX-B1499/21-Y-22062	2022年5月17日	合格	
902	GX-B1499/21-Y-22063	2022年5月17日	合格	