


序号	报告编号	发布日期	结论	影像资料
1	GX-B1329/21-4-23020~23035	2023.5.4	本次共检氧化锌避雷器16组，16组氧化锌避雷器所检项目合格。	
2	GX-B1451/20-4-23057~23069	2023.5.4	本次共检高压开关柜13台，13台所检项目合格。	
3	GX-B1313/21-4-23018~23020	2023.5.4	本次共检电力变压器3台，3台电力变压器所检项目合格。	

4	GX-B1313/21-4-23021~23024	2023. 5. 4	本次共检电力变压器4台，4台电力变压器所检项目合格。	
5	GX-B1559/22-4-23018	2023. 5. 5	所检项目合格	
6	GX-B1559/22-4-23019	2023. 5. 5	所检项目合格	

7	GX-B1321/20-4-23507~23509	2023. 5. 5	本次共检验电力电缆3条，3条所检项目合格。	
8	GX-B1312/20-4-23303~23307	2023. 5. 5	本次共检电力变压器5台，5台所检项目合格。	
9	GX-B1417/22-4-23067	2023. 5. 5	综合判定：合格。 。	

10	GX-B1417/22-4-23068	2023. 5. 5	综合判定：合格。 。	
11	GX-B1417/22-4-23069	2023. 5. 5	综合判定：合格。 。	
12	GX-B1417/22-4-23070	2023. 5. 5	综合判定：合格。 。	

13	GX-B1332/21-4-23037~23060	2023. 5. 5	本次共检电容器 24台，24台所检 项目合格。	
----	---------------------------	------------	-------------------------------	---