





序号	报告编号	发布日期	结论	影像资料
1	GX-B1308/21-Y-23009	2023年5月31日	所检项目合格。	
2	GX-B1499/21-Y-23054	2023年6月1日	所检项目合格。	



3	GX-B1499/21-Y-23055	2023年6月1日	所检项目合格。	
4	GX-B1499/21-Y-23056	2023年6月1日	所检项目合格。	

5	GX-B1499/21-Y-23057	2023年6月1日	所检项目合格。	
6	GX-B1499/21-Y-23058	2023年6月1日	所检项目合格。	

7	GX-B1308/21-Y-23012	2023年6月1日	所检项目合格。	
8	GX-B1499/21-Y-23067	2023年6月1日	所检项目合格。	

9	GX-B1499/21-Y-23068	2023年6月1日	所检项目合格。	 <p>A worker in a blue uniform and red helmet is operating a blue industrial machine. The machine has a red label with the Chinese characters '转动部位' (rotating part). The worker is holding a tool or component. The date '2023/5/23' is visible in the bottom right corner of the photo.</p>
10	GX-B1499/21-Y-23069	2023年6月1日	所检项目合格。	 <p>A worker in a blue uniform and red helmet is inspecting a large industrial machine in a dark environment. The worker is holding a flashlight. The date '2023/5/23' is visible in the bottom right corner of the photo.</p>

11	GX-B1308/21-Y-23011	2023年6月1日	所检项目合格。	 <p>A photograph showing a worker in a dark uniform and helmet inspecting a tunnel. The tunnel has green-painted walls and several large green pipes running along the right side. The worker is holding a flashlight and looking at something in their hands. The date stamp '2023/5/15' is visible in the bottom right corner of the image.</p>
12	GX-B1499/21-Y-23063	2023年6月1日	除吨水百米电耗超限外，其余所检项目合格。	 <p>A photograph showing a worker in a dark uniform and helmet working on a piece of industrial machinery. The machinery is primarily blue and green. The worker is wearing a red safety vest and is focused on a task. The date stamp '2023/5/15' is visible in the bottom right corner of the image.</p>

13	GX-B1499/21-Y-23064	2023年6月1日	除吨水百米电耗超限外，其余所检项目合格。	
14	GX-B1499/21-Y-23065	2023年6月1日	除吨水百米电耗超限外，其余所检项目合格。	

15	GX-B1539/22-Y-23146	2023年6月1日	所检项目合格。	
16	GX-B1539/22-Y-23147	2023年6月1日	所检项目合格。	

17	GX-B1539/22-Y-23148	2023年6月1日	所检项目合格。	
18	GX-B1539/22-Y-23149	2023年6月1日	所检项目合格。	

19	GX-B1539/22-Y-23150	2023年6月1日	所检项目合格。	
20	GX-B1539/22-Y-23151	2023年6月1日	所检项目合格。	

21	GX-B1539/22-Y-23152	2023年6月1日	所检项目合格。	 <p>A photograph showing a yellow wheel loader with the number '7' on its side. Two workers, one in a purple shirt and one in a white uniform with a red hard hat, are standing in front of the loader. The background shows a mining site with hills. A date stamp '2023/5/26' is visible in the bottom right corner of the photo.</p>
22	GX-B1306/21-Y-23086	2023年6月1日	所检项目合格。	 <p>A photograph showing a worker in a white uniform and red hard hat operating a piece of orange machinery. The worker is holding a tool or hose. The machinery has the number '20' on its side. The background shows a blue structure. A date stamp '2023/5/27' is visible in the bottom right corner of the photo.</p>

23	GX-B1306/21-Y-23087	2023年6月1日	所检项目合格。	 <p>A worker wearing a white uniform and a red hard hat is operating a piece of machinery. The worker is leaning over the machine, which has a yellow and black color scheme. A yellow timestamp '2023/5/27' is visible in the bottom right corner of the photo.</p>
24	GX-B1306/21-Y-23088	2023年6月1日	所检项目合格。	 <p>A worker wearing a white uniform and a red hard hat is standing next to a piece of machinery. The worker is holding a hose or cable. The machinery is yellow and black. A yellow timestamp '2023/5/27' is visible in the bottom right corner of the photo.</p>

25	GX-B1306/21-Y-23089	2023年6月1日	所检项目合格。	 <p>A photograph showing a worker in a white protective suit and red helmet operating an orange industrial machine. The machine has a large hopper and a discharge chute. The worker is holding a hose or pipe connected to the machine. The date stamp '2023/5/27' is visible in the bottom right corner of the image.</p>
26	GX-B1306/21-Y-23090	2023年6月1日	所检项目合格。	 <p>A photograph showing a worker in a white protective suit and red helmet inspecting a yellow and blue industrial machine. The machine has a hopper and a discharge chute. The worker is holding a tool or device. The date stamp '2023/5/27' is visible in the bottom right corner of the image.</p>

27	GX-B1306/21-Y-23091	2023年6月1日	所检项目合格。	 A worker in a white uniform and red helmet is operating machinery, possibly a conveyor belt or sorting machine, in an industrial setting. The worker is wearing safety glasses and gloves. A yellow timestamp '2023/9/28' is visible in the bottom right corner of the photo.
28	GX-B1306/21-Y-23092	2023年6月1日	所检项目合格。	 A worker in a white uniform and red helmet is standing next to a yellow vehicle, possibly a small truck or loader, in an industrial setting. The worker is wearing safety glasses and gloves. A red number '7' is visible on the side of the vehicle. A yellow timestamp '2023/5/28' is visible in the bottom right corner of the photo.


29	GX-B1306/21-Y-23093	2023年6月1日	所检项目合格。	 <p>A photograph showing a worker in a white uniform and red helmet operating a piece of machinery. The worker is standing next to a large orange machine, possibly a forklift or a similar industrial vehicle. The background is a blue corrugated metal wall. A yellow timestamp '2023/5/28' is visible in the bottom right corner of the image.</p>
30	GX-B1306/21-Y-23094	2023年6月1日	所检项目合格。	 <p>A photograph showing a worker in a white uniform and red helmet working on a piece of machinery. The worker is leaning over a large orange machine, possibly a forklift or a similar industrial vehicle. The background is a blue corrugated metal wall. A yellow timestamp '2023/5/28' is visible in the bottom right corner of the image.</p>



31	GX-B1306/21-Y-23095	2023年6月1日	所检项目合格。	
32	GX-B1306/21-Y-23096	2023年6月1日	所检项目合格。	

33	GX-B1539/22-Y-23153	2023年6月1日	所检项目合格。	
34	GX-B1539/22-Y-23154	2023年6月1日	所检项目合格。	

35	GX-B1539/22-Y-23155	2023年6月1日	所检项目合格。	
36	GX-B1539/22-Y-23156	2023年6月1日	所检项目合格。	

37	GX-B1539/22-Y-23157	2023年6月1日	所检项目合格。	
38	GX-B1522/20-Y-23094	2023年6月1日	所检项目合格。	

39	GX-B1522/20-Y-23095	2023年6月1日	所检项目合格。	
40	GX-B1522/20-Y-23096	2023年6月1日	所检项目合格。	



41	GX-B1522/20-Y-23097	2023年6月1日	所检项目合格。	
42	GX-B1522/20-Y-23098	2023年6月1日	所检项目合格。	

43	GX-B1522/20-Y-23099	2023年6月1日	所检项目合格。	
44	GX-B1522/20-Y-23100	2023年6月1日	所检项目合格。	



45	GX-B1522/20-Y-23101	2023年6月1日	所检项目合格。	
46	GX-B1522/20-Y-23102	2023年6月1日	所检项目合格。	

47	GX-B1522/20-Y-23103	2023年6月1日	所检项目合格。	
48	GX-B1522/20-Y-23104	2023年6月1日	所检项目合格。	

49	GX-B1522/20-Y-23105	2023年6月1日	所检项目合格。	
50	GX-B1522/20-Y-23106	2023年6月1日	所检项目合格。	

51	GX-B1522/20-Y-23107	2023年6月1日	所检项目合格。	
52	GX-B1522/20-Y-23108	2023年6月1日	所检项目合格。	

53	GX-B1310/21-Y-23080	2023年6月2日	符合标准要求。	 <p>A worker in an orange safety suit and red helmet is using a handheld device to inspect a large, dark, circular industrial component. The worker is standing in an industrial setting with metal railings and equipment visible in the background. A yellow timestamp '2023/5/20' is visible in the bottom right corner of the photo.</p>
54	GX-B1310/21-Y-23081	2023年6月2日	符合标准要求。	 <p>A worker in an orange safety suit and red helmet is operating a green industrial machine. The worker is standing in an industrial setting with large red pipes and equipment visible in the background. A yellow timestamp '2023/5/20' is visible in the bottom right corner of the photo.</p>

55	GX-B1310/21-Y-23082	2023年6月2日	符合标准要求。	
56	GX-B1310/21-Y-23083	2023年6月2日	符合标准要求。	

57	GX-B1310/21-Y-23084	2023年6月2日	符合标准要求。	
58	GX-B1310/21-Y-23085	2023年6月2日	符合标准要求。	



59	GX-B1428/21-Y-23082	2023年6月2日	无缺陷迹痕显示。	
60	GX-B1428/21-Y-23083	2023年6月2日	无缺陷迹痕显示。	

61	GX-B1423/20-Y-233460	2023年6月4日	综合判定：合格	 A yellow truck with a large dump body. The number '9' is visible on the side of the body. Two workers in safety gear stand in front of the truck. A date stamp '2023/5/21' is in the bottom right corner.
62	GX-B1423/20-Y-233461	2023年6月4日	综合判定：合格	 A yellow truck with a large dump body. The number '12' is visible on the side of the body. Two workers in safety gear stand in front of the truck. A date stamp '2023/5/21' is in the bottom right corner.

63	GX-B1423/20-Y-233462	2023年6月4日	综合判定：合格	
64	GX-B1423/20-Y-233463	2023年6月4日	综合判定：合格	

65	GX-B1423/20-Y-233464	2023年6月4日	综合判定：合格	
66	GX-B1423/20-Y-233465	2023年6月4日	综合判定：合格	


67	GX-B1423/20-Y-233466	2023年6月4日	综合判定：合格	
68	GX-B1423/20-Y-233467	2023年6月4日	综合判定：合格	

69	GX-B1423/20-Y-233468	2023年6月4日	综合判定：合格	
70	GX-B1423/20-Y-233469	2023年6月4日	综合判定：合格	

71	GX-B1423/20-Y-233470	2023年6月4日	综合判定：合格	
72	GX-B1423/20-Y-233471	2023年6月4日	综合判定：合格	



73	GX-B1423/20-Y-233472	2023年6月4日	综合判定：合格	
74	GX-B1423/20-Y-233473	2023年6月4日	综合判定：合格	

75	GX-B1423/20-Y-233474	2023年6月4日	综合判定：合格	
76	GX-B1423/20-Y-233475	2023年6月4日	综合判定：合格	



77	GX-B1423/20-Y-233476	2023年6月4日	综合判定：合格	
78	GX-B1423/20-Y-233477	2023年6月4日	综合判定：合格	

79	GX-B1423/20-Y-233478	2023年6月4日	综合判定：合格	
80	GX-B1423/20-Y-233479	2023年6月4日	综合判定：合格	

81	GX-B1423/20-Y-233480	2023年6月4日	综合判定：合格	
82	GX-B1423/20-Y-233481	2023年6月4日	综合判定：合格	

83	GX-B1423/20-Y-233482	2023年6月4日	综合判定：合格	
84	GX-B1423/20-Y-233483	2023年6月4日	综合判定：合格	

85	GX-B1423/20-Y-233484	2023年6月4日	综合判定：合格	
86	GX-B1423/20-Y-233485	2023年6月4日	综合判定：合格	

87	GX-B1423/20-Y-233486	2023年6月4日	综合判定：合格	
88	GX-B1423/20-Y-233487	2023年6月4日	综合判定：合格	

89	GX-B1423/20-Y-233488	2023年6月4日	综合判定：合格	
90	GX-B1423/20-Y-233489	2023年6月4日	综合判定：合格	

91	GX-B1423/20-Y-233490	2023年6月4日	综合判定：合格	
92	GX-B1423/20-Y-233491	2023年6月4日	综合判定：合格	

93	GX-B1423/20-Y-233492	2023年6月4日	综合判定：合格	 A photograph of a yellow truck with the number 82 on its side. Two workers in white protective suits and red hard hats are standing in front of the truck. The truck is parked on a dirt surface. A yellow timestamp '2023/5/23' is visible in the bottom right corner of the image.
94	GX-B1423/20-Y-233493	2023年6月4日	综合判定：合格	 A photograph of a yellow truck with the number 83 on its side. Two workers in white protective suits and red hard hats are standing in front of the truck. The truck is parked on a dirt surface. A yellow timestamp '2023/5/23' is visible in the bottom right corner of the image.

95	GX-B1423/20-Y-233494	2023年6月4日	综合判定：合格	
96	GX-B1423/20-Y-233495	2023年6月4日	综合判定：合格	

97	GX-B1423/20-Y-233496	2023年6月4日	综合判定：合格	
98	GX-B1423/20-Y-233497	2023年6月4日	综合判定：合格	



99	GX-B1423/20-Y-233498	2023年6月4日	综合判定：合格	 <p>A photograph showing a yellow truck with license plate number 53. Two workers, one in a light-colored uniform and a red hard hat, and another in a dark shirt and jeans, are standing in front of the truck. The truck is parked on a dirt road. A yellow timestamp '2023/5/23' is visible in the bottom right corner of the photo.</p>
100	GX-B1423/20-Y-233499	2023年6月4日	综合判定：合格	 <p>A photograph showing a yellow truck with license plate number 38. Two workers, one in a light-colored uniform and a red hard hat, and another in a dark uniform and a black hard hat, are standing in front of the truck. The truck is parked on a dirt road. A yellow timestamp '2023/5/23' is visible in the bottom right corner of the photo.</p>

101	GX-B1423/20-Y-233500	2023年6月4日	综合判定：合格	
102	GX-B1423/20-Y-233501	2023年6月4日	综合判定：合格	

103	GX-B1423/20-Y-233502	2023年6月4日	综合判定：合格	
104	GX-B1423/20-Y-233503	2023年6月4日	综合判定：合格	

105	GX-B1423/20-Y-233504	2023年6月4日	综合判定：合格	
106	GX-B1423/20-Y-233505	2023年6月4日	综合判定：合格	

107	GX-B1423/20-Y-233506	2023年6月4日	综合判定：合格	
108	GX-B1423/20-Y-233507	2023年6月4日	综合判定：合格	

109	GX-B1423/20-Y-233508	2023年6月4日	综合判定：合格	
110	GX-B1423/20-Y-233509	2023年6月4日	综合判定：合格	

111	GX-B1423/20-Y-233510	2023年6月4日	综合判定：合格	
112	GX-B1423/20-Y-233511	2023年6月4日	综合判定：合格	

113	GX-B1423/20-Y-233512	2023年6月4日	综合判定：合格	
114	GX-B1423/20-Y-233513	2023年6月4日	综合判定：合格	

115	GX-B1423/20-Y-233514	2023年6月4日	综合判定：合格	
116	GX-B1423/20-Y-233515	2023年6月4日	综合判定：合格	

117	GX-B1423/20-Y-233516	2023年6月4日	综合判定：合格	
118	GX-B1423/20-Y-233517	2023年6月4日	综合判定：合格	

119	GX-B1423/20-Y-233518	2023年6月4日	综合判定：合格	 <p>A photograph of a yellow TONY truck with the number 99 on its front. Two men wearing hard hats and work clothes are standing in front of the truck. A date stamp '2023/5/24' is visible in the bottom right corner of the photo.</p>
120	GX-B1423/20-Y-233519	2023年6月4日	综合判定：合格	 <p>A photograph of a red LCMG truck with the number 101 on its front. Two men wearing hard hats and work clothes are standing in front of the truck. A date stamp '2023/5/24' is visible in the bottom right corner of the photo.</p>

121	GX-B1423/20-Y-233520	2023年6月4日	综合判定：合格	 <p>A yellow dump truck with the number 107 and the Chinese characters '同力重工' (Tongli Heavy Industry) on its side. Two people are standing in front of the truck. A yellow timestamp '2023/5/25' is visible in the bottom right corner of the photo.</p>
122	GX-B1423/20-Y-233521	2023年6月4日	综合判定：合格	 <p>A yellow dump truck with the number 108 and the Chinese characters '同力重工' (Tongli Heavy Industry) on its side. Two people are standing in front of the truck. A yellow timestamp '2023/5/25' is visible in the bottom right corner of the photo.</p>