

序号	报告编号	发布日期	结论	影像资料
118	GX-B1306/21-4-23036	2023. 6. 9	所检项目合格	
119	GX-B1306/21-4-23037	2023. 6. 9	所检项目合格	
120	GX-B1306/21-4-23038	2023. 6. 9	所检项目合格	

121	GX-B1352/21-4-23825~23826	2023. 6. 9	所检项目合格		
122	GX-B1352/21-4-235031	2023. 6. 9	所检项目合格		
123	GX-B1350/21-4-23054	2023. 6. 7	所检项目合格		
124	GX-B1350/21-4-23055	2023. 6. 7	所检项目合格		

125	GX-B1350/21-4-23056	2023. 6. 12	所检项目合格		 <p>2023. 5. 20</p>	
126	GX-B1350/21-4-23061	2023. 6. 12	本次共检验接地装置7处，7处所检项目合格。	 <p>2023. 5. 16</p>		
127	GX-B1350/21-4-23062	2023. 6. 12	本次共检验接地装置7处，7处所检项目合格。	 <p>2023. 5. 17</p>		
128	GX-B1352/21-4-23861~23880	2023. 6. 14	本次共检矿用防爆低压交流真空馈电开关20台，20台所检项目合格。	 <p>2023. 5. 16</p>		

129	GX-B1352/21-4-23881~23895	2023. 6. 14	本次共检矿用防爆低压交流真空馈电开关20台，20台所检项目合格。		
130	GX-B1517/20-4-23019	2023. 6. 14	综合判定：合格		
131	GX-B1517/20-4-23020	2023. 6. 14	综合判定：合格		
132	GX-B1517/20-4-23021	2023. 6. 14	综合判定：合格		

133	GX-B1517/20-4-23022	2023. 6. 14	综合判定：合格		 <p>2023. 5. 16</p>	
134	GX-B1312/20-4-23557	2023. 6. 13	所检项目合格		 <p>2023. 5. 21</p>	
135	GX-B1321/20-4-23911	2023. 6. 13	所检项目合格		 <p>2023. 5. 21</p>	