


序号	报告编号	发布日期	结论	影像资料
81	GX-B1515/22-2-23008	2023. 8. 14	所检项目合格。	
82	GX-B1515/22-2-23009	2023. 8. 14	所检项目合格。	
83	GX-B1323/21-2-23081~23086	2023. 8. 14	本次共检三相交流电动机6台，6台三相交流电动机所检项目合格。	

84	GX-B1323/21-2-23087~23093	2023. 8. 14	本次共检三相交流电动机7台，7台三相交流电动机所检项目合格。			
85	GX-B1323/21-2-23094~23097	2023. 8. 14	本次共检三相交流电动机4台，4台三相交流电动机所检项目合格。			
86	GX-B1548/20-2-23051	2023. 8. 11	所检项目合格。			

87	GX-B1548/20-2-23052	2023. 8. 11	所检项目合格。	 A photograph showing three men standing next to a blue car with license plate GX-B10009. One man is wearing a red hard hat and a blue and orange work uniform, another is in a black t-shirt and jeans, and the third is in a white t-shirt and dark pants. They appear to be inspecting the vehicle. A timestamp '2023/08/11' is visible in the bottom right corner of the photo.
88	GX-B1548/20-2-23053	2023. 8. 11	所检项目合格。	 A photograph showing two men standing next to a blue car. One man is wearing a yellow hard hat and a white t-shirt, and the other is in a black t-shirt and jeans. They are looking at something in the man's hands. A timestamp '2023/08/11' is visible in the bottom right corner of the photo.
89	GX-B1548/20-2-23054	2023. 8. 11	所检项目合格。	 A photograph showing two men standing next to a blue car. One man is wearing a yellow hard hat and a white t-shirt, and the other is in a black t-shirt and jeans. They are looking at something in the man's hands. A timestamp '2023/08/11' is visible in the bottom right corner of the photo.

90	GX-B1548/20-2-23055	2023. 8. 11	所检项目合格。	 2023/08/11
91	GX-B1548/20-2-23056	2023. 8. 11	所检项目合格。	 2023/08/11
92	GX-B1548/20-2-23057	2023. 8. 11	所检项目合格。	 2023/08/11

93	GX-B1548/20-2-23091	2023. 8. 14	所检项目合格。		
94	GX-B1548/20-2-23092	2023. 8. 14	所检项目合格。		
95	GX-B1548/20-2-23093	2023. 8. 14	所检项目合格。		

96	GX-B1548/20-2-23094	2023. 8. 14	所检项目合格。	
97	GX-B1548/20-2-23095	2023. 8. 14	所检项目合格。	
98	GX-B1428/21-2-23145	2023/8/15	无缺陷迹痕显示。	

99	GX-B1428/21-2-23146	2023/8/15	无缺陷迹痕显示。	
100	GX-B1428/21-2-23147	2023/8/15	无缺陷迹痕显示。	
101	GX-B1428/21-2-23148	2023/8/15	无缺陷迹痕显示。	

102	GX-B1428/21-2-23149	2023/8/15	无缺陷迹痕显示。	
103	GX-B1428/21-2-23150	2023/8/15	无缺陷迹痕显示。	
104	GX-B1428/21-2-23151	2023/8/15	无缺陷迹痕显示。	


105	GX-B1310/21-2-23152	2023/8/15	符合标准要求。	
106	GX-B1310/21-2-23153	2023/8/15	符合标准要求。	
107	GX-B1427/21-2-23152	2023/8/15	符合标准要求。	

108	GX-B1427/21-2-23153	2023/8/15	符合标准要求。	
109	GX-B1323/21-2-23098~23102	2023. 8. 14	所检项目合格	
110	GX-B1310/21-2-23154	2023. 8. 16	符合标准要求。	

111	GX-B1328/20-2-23112	2023. 8. 16	所检项目合格		
112	GX-B1328/20-2-23113	2023. 8. 16	所检项目合格		
113	GX-B1328/20-2-23114	2023. 8. 16	所检项目合格		

114	GX-B1328/20-2-23115	2023. 8. 16	所检项目合格		 A photograph showing an electrical room with various pieces of equipment, safety barriers, and a person in the background. The date stamp in the bottom right corner reads 2023/07/23.	
115	GX-B1328/20-2-23116	2023. 8. 16	所检项目合格		 A photograph showing an electrical room with various pieces of equipment, safety barriers, and a person in the background. The date stamp in the bottom right corner reads 2023/07/23.	
116	GX-B1328/20-2-23106	2023. 8. 16	所检项目合格		 A photograph showing two workers in safety gear standing in an electrical room. They are positioned near some equipment and safety barriers. The date stamp in the bottom right corner reads 2023/07/23.	

117	GX-B1328/20-2-23107	2023. 8. 16	所检项目合格	 <p>2023/07/12</p>
118	GX-B1321/20-2-23427~23428	2023. 8. 16	所检项目合格	 <p>2023/07/07</p>
119	GX-B1321/20-2-23429~23435	2023. 8. 16	所检项目合格	 <p>2023/07/08</p>

120	GX-B1321/20-2-23436~23442	2023. 8. 16	所检项目合格	 A worker wearing a red hard hat and a blue uniform is working on a piece of machinery. The worker is looking towards the camera. The date stamp in the bottom right corner of the image is 2023/07/09.
121	GX-B1312/20-2-23191~23199	2023. 8. 16	所检项目合格	 A worker in a blue uniform and red hard hat is working on a large piece of machinery. The worker is looking down at the machinery. The date stamp in the bottom right corner of the image is 2023/07/19.
122	GX-B1312/20-2-23200~23208	2023. 8. 16	所检项目合格	 A worker in a blue uniform and red hard hat is kneeling on the floor next to a large red piece of machinery. The worker is looking towards the camera. The date stamp in the bottom right corner of the image is 2023/07/08.

123	GX-B1312/20-2-23209~23215	2023. 8. 16	所检项目合格	
124	GX-B1495/20-2-231175~231184	2023. 8. 18	所检项目合格	
125	GX-B1495/20-2-231185~231190	2023. 8. 18	所检项目合格	

126	GX-B1495/20-2-231191~231195	2023. 8. 18	所检项目合格	 2023/07/12
127	GX-B1495/20-2-231196~231205	2023. 8. 18	所检项目合格	 2023/07/10
128	GX-B1495/20-2-231206~231213	2023. 8. 18	所检项目合格	 2023/07/11

129	GX-B1495/20-2-231214~231218	2023. 8. 18	所检项目合格		
130	GX-B1321/20-2-23443~23450	2023. 8. 18	所检项目合格		
131	GX-B1321/20-2-23451~23454	2023. 8. 18	所检项目合格		

132	GX-B1321/20-2-23455~23459	2023. 8. 18	所检项目合格	
133	GX-B1312/20-2-23232~23237	2023. 8. 18	所检项目合格	
134	GX-B1321/20-2-23376~23377	2023. 8. 16	所检项目合格	

135	GX-B1321/20-2-23378~23380	2023. 8. 16	所检项目合格	
136	GX-B1321/20-2-23381~23382	2023. 8. 16	所检项目合格	
137	GX-B1321/20-2-23383~23388	2023. 8. 16	所检项目合格	

138	GX-B1321/20-2-23389~23394	2023. 8. 16	所检项目合格	 2023/06/26
139	GX-B1321/20-2-23395~23397	2023. 8. 16	所检项目合格	 2023/06/27
140	GX-B1321/20-2-23398~23401	2023. 8. 16	所检项目合格	 2023/06/28

141	GX-B1321/20-2-23402~23403	2023. 8. 16	所检项目合格	 <p>2023/06/29</p>
142	GX-B1321/20-2-23404	2023. 8. 16	所检项目合格	 <p>2023/06/30</p>
143	GX-B1321/20-2-23405~23408	2023. 8. 16	所检项目合格	 <p>2023/07/01</p>

144	GX-B1321/20-2-23409~23412	2023. 8. 16	所检项目合格	
145	GX-B1321/20-2-23413~23417	2023. 8. 16	所检项目合格	
146	GX-B1321/20-2-23418~23420	2023. 8. 16	所检项目合格	

147	GX-B1321/20-2-23421~23424	2023. 8. 16	所检项目合格	
148	GX-B1321/20-2-23425~23426	2023. 8. 16	所检项目合格	
149	GX-B1312/20-2-23179~23180	2023. 8. 16	所检项目合格	

150	GX-B1312/20-2-23181~23182	2023. 8. 16	所检项目合格	
151	GX-B1312/20-2-23183~23184	2023. 8. 16	所检项目合格	
152	GX-B1312/20-2-23185~23186	2023. 8. 16	所检项目合格	


153	GX-B1312/20-2-23187~23190	2023. 8. 16	所检项目合格	
154	GX-B1307/20-2-23069	2023. 8. 18	综合判定：合格。	
155	GX-B1307/20-2-23071	2023. 8. 18	综合判定：合格。	

156	GX-B1307/20-2-23072	2023. 8. 18	综合判定：合格。	
157	GX-B1352/21-2-23174~23176	2023. 8. 18	本次共检矿用防爆低压 交流真空馈电开关 3台，3台所检项目合格。 。	
158	GX-B1329/21-2-23119~23124	2023. 8. 18	本次共检氧化锌避雷器 6组，6组所检项目合格。 。	

159	GX-B1302/21-2-23007	2023. 8. 18	综合判定：合格。	 2023/07/18
160	GX-B1548/20-2-23079	2023. 8. 18	所检项目合格。	 2023/05/24
161	GX-B1548/20-2-23080	2023. 8. 18	所检项目合格。	 2023/05/24

162	GX-B1548/20-2-23081	2023. 8. 18	所检项目合格。	
163	GX-B1548/20-2-23082	2023. 8. 18	所检项目合格。	
164	GX-B1548/20-2-23083	2023. 8. 18	所检项目合格。	

165	GX-B1534/20-2-23040	2023. 8. 18	所检项目合格。		
166	GX-B1534/20-2-23041	2023. 8. 18	所检项目合格。		
167	GX-B1534/20-2-23042	2023. 8. 18	所检项目合格。		

168	GX-B1534/20-2-23043	2023. 8. 18	所检项目合格。		
169	GX-B1534/20-2-23044	2023. 8. 18	所检项目合格。		
170	GX-B1548/20-2-23073	2023. 8. 18	所检项目合格。		

171	GX-B1548/20-2-23074	2023. 8. 18	所检项目合格。		
172	GX-B1548/20-2-23075	2023. 8. 18	所检项目合格。		
173	GX-B1548/20-2-23076	2023. 8. 18	所检项目合格。		

174	GX-B1548/20-2-23077	2023. 8. 18	所检项目合格。		
175	GX-B1548/20-2-23078	2023. 8. 18	所检项目合格。		
176	GX-B1534/20-2-23029	2023. 8. 18	所检项目合格。		

177	GX-B1534/20-2-23030	2023. 8. 18	所检项目合格。		
178	GX-B1534/20-2-23031	2023. 8. 18	所检项目合格。		
179	GX-B1534/20-2-23032	2023. 8. 18	所检项目合格。		

180	GX-B1548/20-2-23069	2023. 8. 18	所检项目合格。	
181	GX-B1548/20-2-23070	2023. 8. 18	所检项目合格。	
182	GX-B1548/20-2-23071	2023. 8. 18	所检项目合格。	

183	GX-B1548/20-2-23072	2023. 8. 18	所检项目合格。		
184	GX-B1534/20-2-23033	2023. 8. 18	所检项目合格。		
185	GX-B1534/20-2-23034	2023. 8. 18	所检项目合格。		

186	GX-B1534/20-2-23035	2023. 8. 18	所检项目合格。	
187	GX-B1534/20-2-23036	2023. 8. 18	所检项目合格。	
188	GX-B1534/20-2-23037	2023. 8. 18	所检项目合格。	

189	GX-B1534/20-2-23038	2023. 8. 18	所检项目合格。	
190	GX-B1534/20-2-23039	2023. 8. 18	所检项目合格。	
191	GX-B1548/20-2-23084	2023. 8. 18	所检项目合格。	


192	GX-B1548/20-2-23085	2023. 8. 18	所检项目合格。	
193	GX-B1548/20-2-23086	2023. 8. 18	所检项目合格。	
194	GX-B1548/20-2-23087	2023. 8. 18	所检项目合格。	

195	GX-B1534/20-2-23028	2023. 8. 18	所检项目合格。	
196	GX-B1548/20-2-23038	2023. 8. 18	所检项目合格。	
197	GX-B1548/20-2-23039	2023. 8. 18	所检项目合格。	

198	GX-B1548/20-2-23040	2023. 8. 18	所检项目合格。	
199	GX-B1548/20-2-23041	2023. 8. 18	所检项目合格。	
200	GX-B1548/20-2-23042	2023. 8. 18	所检项目合格。	

201	GX-B1548/20-2-23043	2023. 8. 18	所检项目合格。	 <p>2023/08/25</p>
202	GX-B1548/20-2-23044	2023. 8. 18	所检项目合格。	 <p>2023/08/25</p>
203	GX-B1548/20-2-23045	2023. 8. 18	所检项目合格。	 <p>2023/08/25</p>

204	GX-B1548/20-2-23029	2023. 8. 21	所检项目合格。		
205	GX-B1548/20-2-23030	2023. 8. 21	所检项目合格。		
206	GX-B1548/20-2-23031	2023. 8. 21	所检项目合格。		

207	GX-B1548/20-2-23032	2023. 8. 21	所检项目合格。			
208	GX-B1534/20-2-23022	2023. 8. 21	所检项目合格。			
209	GX-B1548/20-2-23037	2023. 8. 21	所检项目合格。			

210	GX-B1534/20-2-23045	2023. 8. 21	所检项目合格。	
211	GX-B1534/20-2-23046	2023. 8. 21	所检项目合格。	
212	GX-B1534/20-2-23047	2023. 8. 21	所检项目合格。	

213	GX-B1534/20-2-23048	2023. 8. 21	所检项目合格。	 A photograph showing two men in light-colored shirts and dark trousers standing in a paved area next to a yellow truck. The truck has a license plate that reads '桂A 1270'. The background shows a large industrial building with a corrugated metal roof. A timestamp '2023/08/21' is visible in the bottom right corner of the image.
214	GX-B1534/20-2-23049	2023. 8. 21	所检项目合格。	 A photograph showing a man in a light-colored shirt and dark trousers standing in a paved area next to a yellow truck. Another person is visible in the background. The truck has a license plate that reads '桂A 1270'. The background shows a large industrial building with a corrugated metal roof. A timestamp '2023/08/21' is visible in the bottom right corner of the image.
215	GX-B1534/20-2-23050	2023. 8. 21	所检项目合格。	 A photograph showing a man in a light-colored shirt and dark trousers standing in a paved area next to a yellow truck. Another person is visible in the background. The truck has a license plate that reads '桂A 1270'. The background shows a large industrial building with a corrugated metal roof. A timestamp '2023/08/21' is visible in the bottom right corner of the image.


216	GX-B1534/20-2-23051	2023. 8. 21	所检项目合格。	 <p>2023/08/21</p>
217	GX-B1534/20-2-23052	2023. 8. 21	所检项目合格。	 <p>2023/08/21</p>
218	GX-B1534/20-2-23053	2023. 8. 21	所检项目合格。	 <p>2023/08/21</p>

219	GX-B1534/20-2-23054	2023. 8. 21	所检项目合格。	 <p>2023/08/10</p>
220	GX-B1534/20-2-23055	2023. 8. 21	所检项目合格。	 <p>2023/08/10</p>
221	GX-B1534/20-2-23056	2023. 8. 21	所检项目合格。	 <p>2023/08/10</p>

222	GX-B1534/20-2-23057	2023. 8. 21	所检项目合格。	
223	GX-B1534/20-2-23058	2023. 8. 21	所检项目合格。	
224	GX-B1534/20-2-23059	2023. 8. 21	所检项目合格。	

225	GX-B1534/20-2-23060	2023. 8. 21	所检项目合格。	
226	1	2023. 8. 16	所检项目合格	
227	GX-B1495/20-2-23804~23807	2023. 8. 16	所检项目合格	

228	GX-B1495/20-2-23808~23809	2023. 8. 16	所检项目合格	
229	GX-B1495/20-2-23810~23819	2023. 8. 16	所检项目合格	
230	GX-B1495/20-2-23820~23827	2023. 8. 16	所检项目合格	

231	GX-B1495/20-2-23828~23831	2023. 8. 16	所检项目合格		
232	GX-B1495/20-2-23832~23840	2023. 8. 16	所检项目合格		
233	GX-B1495/20-2-23841~23851	2023. 8. 16	所检项目合格		

234	GX-B1495/20-2-23852~23861	2023. 8. 16	所检项目合格	
235	GX-B1495/20-2-23862~23879	2023. 8. 16	所检项目合格	
236	GX-B1495/20-2-23880~23903	2023. 8. 16	所检项目合格	

237	GX-B1495/20-2-23904~23923	2023. 8. 16	所检项目合格	
238	GX-B1495/20-2-23924~23933	2023. 8. 16	所检项目合格	
239	GX-B1495/20-2-23934~23939	2023. 8. 16	所检项目合格	

240	GX-B1495/20-2-23940~23946	2023. 8. 16	所检项目合格	
241	GX-B1495/20-2-23947~23951	2023. 8. 16	所检项目合格	
242	GX-B1495/20-2-23952~23971	2023. 8. 16	所检项目合格	

243	GX-B1495/20-2-23972~23985	2023. 8. 16	所检项目合格	
244	GX-B1495/20-2-23986~23999	2023. 8. 16	所检项目合格	
245	GX-B1495/20-2-231000~231009	2023. 8. 16	所检项目合格	

246	GX-B1495/20-2-231010~231014	2023. 8. 16	所检项目合格	 <p>2023/07/01</p>
247	GX-B1495/20-2-231015~231020	2023. 8. 16	所检项目合格	 <p>2023/07/02</p>
248	GX-B1495/20-2-231021~231025	2023. 8. 16	所检项目合格	 <p>2023/07/03</p>

249	GX-B1495/20-2-231026~231037	2023. 8. 16	所检项目合格	 <p>2023/07/11</p>
250	GX-B1495/20-2-231038~231047	2023. 8. 16	所检项目合格	 <p>2023/07/02</p>
251	GX-B1495/20-2-231048~231057	2023. 8. 16	所检项目合格	 <p>2023/07/11</p>

252	GX-B1495/20-2-231058~231066	2023. 8. 16	所检项目合格	
253	GX-B1495/20-2-231067~231073	2023. 8. 16	所检项目合格	
254	GX-B1495/20-2-231074~231078	2023. 8. 16	所检项目合格	

255	GX-B1495/20-2-231079~231096	2023. 8. 16	所检项目合格	
256	GX-B1495/20-2-231097~231110	2023. 8. 16	所检项目合格	
257	GX-B1495/20-2-231111~231120	2023. 8. 16	所检项目合格	

258	GX-B1495/20-2-231121~231125	2023. 8. 16	所检项目合格	
259	GX-B1495/20-2-231126~231135	2023. 8. 16	所检项目合格	
260	GX-B1495/20-2-231136~231139	2023. 8. 16	所检项目合格	

261	GX-B1495/20-2-231140~231147	2023. 8. 16	所检项目合格	
262	GX-B1495/20-2-231148~231156	2023. 8. 16	所检项目合格	
263	GX-B1495/20-2-231157~231174	2023. 8. 16	所检项目合格	

264	GX-B1495/20-2-23799~23803	2023. 6. 21	本次共检高压防爆开关5台，5台高压防爆开关所检项目合格。	
265	GX-B1307/20-2-23070	2023/8/14	综合判定：合格	
266	GX-B1520/20-2-23008	2023/8/14	综合判定：合格	

267	GX-B1520/20-2-23009	2023/8/14	综合判定：合格	
268	GX-B1520/20-2-23010	2023/8/14	综合判定：合格	
269	GX-B1416/22-2-23026	2023/8/14	综合判定：合格	

270	GX-B1416/22-2-23027	2023/8/14	综合判定：合格	
271	GX-B1416/22-2-23028	2023/8/14	综合判定：合格	
272	GX-B1416/22-2-23029	2023/8/14	综合判定：合格	

273	GX-B1416/22-2-23030	2023/8/14	综合判定：合格	 <p>2023/07/24</p>
274	GX-B1416/22-2-23031	2023/8/14	综合判定：合格	 <p>2023/07/25</p>
275	GX-B1416/22-2-23032	2023/8/14	综合判定：合格	 <p>2023/07/25</p>

276	GX-B1306/20-2-23044	2023/8/14	所检项目合格	
277	GX-B1306/20-2-23045	2023/8/14	所检项目合格	
278	GX-B1306/20-2-23046	2023/8/14	所检项目合格	

279	GX-B1306/20-2-23047	2023/8/14	所检项目合格	
280	GX-B1306/20-2-23048	2023/8/14	所检项目合格	
281	GX-B1306/20-2-23049	2023/8/14	所检项目合格	

282	GX-B1321/20-2-23520~23526	2023. 8. 21	本次共检验电力电缆7条，7条所检项目合格。 。	
283	GX-B1321/20-2-23527~23536	2023. 8. 21	本次共检验电力电缆10条，10条所检项目合格。 。	
284	GX-B1321/20-2-23537~23546	2023. 8. 21	本次共检验电力电缆10条，10条所检项目合格。 。	

285	GX-B1321/20-2-23547~23550	2023. 8. 21	本次共检验电力电缆4条，4条所检项目合格。 。	
286	GX-B1321/20-2-23551~23561	2023. 8. 21	本次共检验电力电缆11条，11条所检项目合格。 。	
287	GX-B1321/20-2-23562~23570	2023. 8. 21	本次共检验电力电缆9条，9条所检项目合格。 。	

288	GX-B1321/20-2-23571~23580	2023. 8. 21	本次共检验电力电缆10条，10条所检项目合格。 。	
289	GX-B1321/20-2-23581~23584	2023. 8. 21	本次共检验电力电缆4条，4条所检项目合格。 。	
290	GX-B1300/20-2-23010	2023. 8. 21	综合判定：不合格。	

291	GX-B1310/21-2-23155	2023/8/19	符合标准要求	
292	GX-B1310/21-2-23156	2023/8/19	符合标准要求	
293	GX-B1310/21-2-23157	2023/8/19	符合标准要求	


294	GX-B1310/21-2-23158	2023/8/19	符合标准要求	
295	GX-B1310/21-2-23159	2023/8/19	未发现超过Φ2mm当量直径的缺陷	
296	GX-B1310/21-2-23160	2023/8/19	未发现超过Φ2mm当量直径的缺陷	

297	GX-B1310/21-2-23161	2023/8/19	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷	
298	GX-B1310/21-2-23162	2023/8/19	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷	
299	GX-B1310/21-2-23170	2023/8/19	符合标准要求	

300	GX-B1310/21-2-23171	2023/8/19	符合标准要求	
301	GX-B1310/21-2-23172	2023/8/19	符合标准要求	
302	GX-B1310/21-2-23173	2023/8/19	符合标准要求	


303	GX-B1310/21-2-23174	2023/8/19	符合标准要求	 2023/07/24
304	GX-B1310/21-2-23175	2023/8/19	符合标准要求	 2023/07/25
305	GX-B1310/21-2-23176	2023/8/19	符合标准要求	 2023/07/25

306	GX-B1427/21-2-23155	2023/8/19	符合标准要求。	
307	GX-B1427/21-2-23156	2023/8/19	符合标准要求。	
308	GX-B1427/21-2-23157	2023/8/19	符合标准要求。	

309	GX-B1427/21-2-23158	2023/8/19	符合标准要求。	
310	GX-B1428/21-2-23159	2023/8/19	无缺陷迹痕显示。	
311	GX-B1428/21-2-23160	2023/8/19	无缺陷迹痕显示。	

312	GX-B1428/21-2-23161	2023/8/19	无缺陷痕迹显示。	
313	GX-B1428/21-2-23162	2023/8/19	无缺陷痕迹显示。	
314	GX-B1350/21-2-23033	2023. 8. 21	本次共检接地装置 2处，2处接地装置所检 项目合格	

315	GX-B1350/21-2-23034	2023. 8. 21	本次共检接地装置 2处，2处接地装置所检 项目合格		
316	GX-B1350/21-2-23035	2023. 8. 21	本次共检接地装置 2处，2处接地装置所检 项目合格		
317	GX-B1350/21-2-23036	2023. 8. 21	本次共检接地装置 2处，2处接地装置所检 项目合格		

318	GX-B1350/21-2-23037	2023. 8. 21	本次共检接地装置 2处，2处接地装置所检 项目合格	 2023/8/1
319	GX-B1350/21-2-23038	2023. 8. 21	本次共检接地装置 2处，2处接地装置所检 项目合格	 2023/8/2
320	GX-B1350/21-2-23039	2023. 8. 21	本次共检接地装置 2处，2处接地装置所检 项目合格	 2023/8/4