



序号	报告编号	发布日期	结论	影像资料
581	GX-B1539/22-Y-23228	2023年8月18日	所检项目合格。	
582	GX-B1521/20-Y-23515	2023年8月18日	所检项目合格。	

583	GX-B1521/20-Y-23516	2023年8月18日	所检项目合格。	 A red tracked excavator is shown in a desert environment under a blue sky with scattered clouds. A person in a yellow safety vest stands next to the machine. A yellow timestamp '2023/8/2' is visible in the bottom right corner of the photo.
584	GX-B1521/20-Y-23517	2023年8月18日	所检项目合格。	 A yellow tracked excavator is shown in a desert environment under a clear blue sky. A person in a yellow safety vest stands next to the machine. A yellow timestamp '2023/8/2' is visible in the bottom right corner of the photo.

585	GX-B1521/20-Y-23518	2023年8月18日	所检项目合格。	 A yellow tracked excavator is parked on a sandy construction site. A worker in a high-visibility vest and hard hat stands near the machine. The sky is clear and blue. A yellow timestamp '2023/8/2' is visible in the bottom right corner of the photo.
586	GX-B1521/20-Y-23519	2023年8月18日	所检项目合格。	 A yellow tracked excavator is parked on a dark, rocky construction site. Two workers in high-visibility vests and hard hats are standing near the machine. The sky is blue with some clouds. A yellow timestamp '2023/8/2' is visible in the bottom right corner of the photo.

587	GX-B1521/20-Y-23520	2023年8月18日	所检项目合格。	
588	GX-B1328/20-Y-23094	2023年8月17日	本次共检验电器7支，7支验电器合格。	

589	GX-B1328/20-Y-23095	2023年8月18日	所检项目合格。	
590	GX-B1521/20-Y-23406	2023年8月16日	所检项目合格。	

591	GX-B1521/20-Y-23407	2023年8月16日	所检项目合格。	
592	GX-B1521/20-Y-23408	2023年8月16日	所检项目合格。	



593	GX-B1521/20-Y-23409	2023年8月16日	所检项目合格。	 A photograph of a red Hitachi excavator at a construction site. The excavator is positioned on a dirt surface, and a person in a yellow safety vest is standing nearby. The background shows a hazy, overcast sky and some distant structures. A yellow timestamp '2023/7/10' is visible in the bottom right corner of the image.
594	GX-B1521/20-Y-23410	2023年8月16日	所检项目合格。	 A photograph of a red Hitachi excavator at a construction site. The excavator is positioned on a dirt surface, and a person in a yellow safety vest is standing nearby. The background shows a hazy, overcast sky and some distant structures. A yellow timestamp '2023/7/10' is visible in the bottom right corner of the image.

595	GX-B1521/20-Y-23411	2023年8月16日	所检项目合格。	 A photograph of a red Hitachi 12 excavator on a construction site. Two workers in safety gear are standing near the machine. A yellow timestamp '2023/7/10' is visible in the bottom right corner of the image.
596	GX-B1521/20-Y-23412	2023年8月16日	所检项目合格。	 A photograph of a red Hitachi 13 excavator on a construction site. Two workers in safety gear are standing near the machine. A yellow timestamp '2023/7/10' is visible in the bottom right corner of the image.

597	GX-B1521/20-Y-23413	2023年8月16日	所检项目合格。	 A photograph of a red Hitachi excavator on a dirt construction site. Two workers in safety gear stand near the machine. A yellow timestamp '2023/7/10' is visible in the bottom right corner of the photo.
598	GX-B1521/20-Y-23414	2023年8月16日	所检项目合格。	 A photograph of a red Hitachi excavator on a dirt construction site. Two workers in safety gear stand near the machine, and a third person is walking in the foreground. A yellow timestamp '2023/7/10' is visible in the bottom right corner of the photo.

599	GX-B1539/22-Y-23173	2023年8月16日	所检项目合格。	
600	GX-B1539/22-Y-23174	2023年8月16日	所检项目合格。	

601	GX-B1539/22-Y-23175	2023年8月16日	所检项目合格。	
602	GX-B1539/22-Y-23176	2023年8月16日	所检项目合格。	

603	GX-B1539/22-Y-23177	2023年8月16日	所检项目合格。	
604	GX-B1385/21-Y-23080	2023年8月16日	所检项目合格。	

605	GX-B1423/20-Y-234947	2023年8月21日	综合判定：合格	
606	GX-B1423/20-Y-234948	2023年8月21日	综合判定：合格	

607	GX-B1423/20-Y-234949	2023年8月21日	综合判定：合格	
608	GX-B1423/20-Y-234950	2023年8月21日	综合判定：合格	

609	GX-B1423/20-Y-234951	2023年8月21日	综合判定：合格	
610	GX-B1423/20-Y-234952	2023年8月21日	综合判定：合格	

611	GX-B1423/20-Y-234953	2023年8月21日	综合判定：合格	
612	GX-B1423/20-Y-234954	2023年8月21日	综合判定：合格	

613	GX-B1423/20-Y-234955	2023年8月21日	综合判定：合格	
614	GX-B1423/20-Y-234956	2023年8月21日	综合判定：合格	

615	GX-B1423/20-Y-234957	2023年8月21日	综合判定：合格	
616	GX-B1423/20-Y-234708	2023年8月17日	综合判定：合格	

617	GX-B1423/20-Y-234709	2023年8月17日	综合判定：合格	
618	GX-B1423/20-Y-234710	2023年8月17日	综合判定：合格	

619	GX-B1423/20-Y-234711	2023年8月17日	综合判定：合格	
620	GX-B1423/20-Y-234712	2023年8月17日	综合判定：合格	

621	GX-B1423/20-Y-234713	2023年8月17日	综合判定：合格	
622	GX-B1423/20-Y-234714	2023年8月17日	综合判定：合格	

623	GX-B1423/20-Y-234715	2023年8月17日	综合判定：合格	
624	GX-B1423/20-Y-234716	2023年8月17日	综合判定：合格	

625	GX-B1423/20-Y-234717	2023年8月17日	综合判定：合格	 A yellow dump truck with its bed raised, parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck has the number '1604' on its side. A yellow timestamp '2023/8/3' is visible in the bottom right corner of the photo.
626	GX-B1423/20-Y-234718	2023年8月17日	综合判定：合格	 A red dump truck with its bed raised, parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck has the number '1606' on its side. A yellow timestamp '2023/8/3' is visible in the bottom right corner of the photo.

627	GX-B1423/20-Y-234719	2023年8月17日	综合判定：合格	
628	GX-B1423/20-Y-234761	2023年8月17日	综合判定：合格	

629	GX-B1423/20-Y-234762	2023年8月17日	综合判定：合格	 A yellow dump truck with the number 4036 on its side, parked on a dirt surface. Two workers in red and white protective suits are standing next to it. The date 2023/8/4 is visible in the bottom right corner of the photo.
630	GX-B1423/20-Y-234763	2023年8月17日	综合判定：合格	 A yellow dump truck with the number 4031 on its side, parked on a dirt surface. Two workers in red and white protective suits are standing next to it. The date 2023/8/4 is visible in the bottom right corner of the photo.

631	GX-B1423/20-Y-234764	2023年8月17日	综合判定：合格	
632	GX-B1423/20-Y-234765	2023年8月17日	综合判定：合格	

633	GX-B1423/20-Y-234766	2023年8月17日	综合判定：合格	 A yellow dump truck with the number 4037 painted on its side. Two workers in high-visibility clothing are standing in front of the truck. A yellow timestamp '2023/8/4' is visible in the bottom right corner of the photo.
634	GX-B1423/20-Y-234767	2023年8月17日	综合判定：合格	 A yellow dump truck with the number 2304 painted on its side. Two workers in high-visibility clothing are standing in front of the truck. A yellow timestamp '2023/8/4' is visible in the bottom right corner of the photo.

635	GX-B1423/20-Y-234768	2023年8月17日	综合判定：合格	
636	GX-B1423/20-Y-234769	2023年8月17日	综合判定：合格	

637	GX-B1423/20-Y-234770	2023年8月17日	综合判定：合格	 <p>A yellow dump truck with the number '5304' painted on its side. Two workers in safety gear are standing in front of the truck. The date '2023/8/4' is visible in the bottom right corner of the photo.</p>
638	GX-B1423/20-Y-234771	2023年8月17日	综合判定：合格	 <p>A yellow dump truck with the number '0404' painted on its side. Two workers in safety gear are standing in front of the truck. The date '2023/8/4' is visible in the bottom right corner of the photo.</p>

639	GX-B1423/20-Y-234772	2023年8月17日	综合判定：合格	
640	GX-B1423/20-Y-234773	2023年8月17日	综合判定：合格	

641	GX-B1423/20-Y-234774	2023年8月17日	综合判定：合格	
642	GX-B1522/20-Y-23123	2023年8月18日	所检项目合格。	

643	GX-B1522/20-Y-23124	2023年8月18日	所检项目合格。	
644	GX-B1522/20-Y-23125	2023年8月18日	所检项目合格。	

645	GX-B1328/20-Y-23104	2023年8月18日	本次共检绝缘手套74只，74只绝缘手套合格。	
646	GX-B1328/20-Y-23105	2023年8月18日	本次共检绝缘鞋74只，74只绝缘鞋合格。	

647	GX-B1328/20-Y-23106	2023年8月18日	本次共检验电器30支，30支验电器合格。	 A photograph showing an indoor industrial setting. In the background, there is a large blue electrical cabinet with Chinese characters on it. Two workers in grey uniforms and red hard hats are standing near the cabinet. In the foreground, a worker in a grey uniform and red hard hat is kneeling on the floor, working with a piece of equipment. There are blue metal boxes and a red fire extinguisher on the floor. A date stamp '2023/8/7' is visible in the bottom right corner of the photo.
648	GX-B1328/20-Y-23107	2023年8月18日	本次共检绝缘胶垫50件，50件绝缘胶垫合格。	 A photograph showing an indoor industrial setting. A worker in a grey uniform and red hard hat is kneeling on the floor, working with a piece of equipment. There are blue metal boxes and a red fire extinguisher on the floor. In the background, there is a large blue electrical cabinet with Chinese characters on it. A date stamp '2023/8/7' is visible in the bottom right corner of the photo.

649	GX-B1328/20-Y-23100	2023年8月17日	本次共检绝缘手套80只，80只绝缘手套合格。	 A photograph showing a worker in a red hard hat and light-colored shirt kneeling on a concrete surface, inspecting equipment. In the background, there are two red gas cylinders on a stand, a yellow chair, and a building with barred windows. A yellow timestamp '2023/8/17' is visible in the bottom right corner of the photo.
650	GX-B1328/20-Y-23101	2023年8月17日	本次共检绝缘鞋68只，68只绝缘鞋合格。	 A photograph showing a worker in a red hard hat and light-colored shirt kneeling on a concrete surface, inspecting equipment. In the background, there are two red gas cylinders on a stand, a yellow chair, and a building with barred windows. A yellow timestamp '2023/8/17' is visible in the bottom right corner of the photo.

651	GX-B1328/20-Y-23102	2023年8月17日	本次共检验电器13只，13只验电器合格。	
652	GX-B1328/20-Y-23096	2023年8月18日	本次共检绝缘手套4只，4只绝缘手套合格。	

653	GX-B1328/20-Y-23097	2023年8月18日	本次共检绝缘鞋4只，4只绝缘鞋合格。	
654	GX-B1328/20-Y-23098	2023年8月18日	所检项目合格。	

655	GX-B1328/20-Y-23099	2023年8月18日	所检项目合格。	
656	GX-B1521/20-Y-23406	2023年8月16日	所检项目合格。	

657	GX-B1521/20-Y-23407	2023年8月16日	所检项目合格。	
658	GX-B1521/20-Y-23408	2023年8月16日	所检项目合格。	



659	GX-B1521/20-Y-23409	2023年8月16日	所检项目合格。	
660	GX-B1521/20-Y-23410	2023年8月16日	所检项目合格。	

661	GX-B1521/20-Y-23411	2023年8月16日	所检项目合格。	 A photograph of a red Hitachi 12 excavator on a construction site. Two workers in safety gear are standing near the machine. A yellow timestamp '2023/7/10' is visible in the bottom right corner of the photo.
662	GX-B1521/20-Y-23412	2023年8月16日	所检项目合格。	 A photograph of a red Hitachi 13 excavator on a construction site. Two workers in safety gear are standing near the machine. A yellow timestamp '2023/7/10' is visible in the bottom right corner of the photo.

663	GX-B1521/20-Y-23413	2023年8月16日	所检项目合格。	
664	GX-B1521/20-Y-23414	2023年8月16日	所检项目合格。	

665	GX-B1539/22-Y-23173	2023年8月16日	所检项目合格。	
666	GX-B1539/22-Y-23174	2023年8月16日	所检项目合格。	

667	GX-B1539/22-Y-23175	2023年8月16日	所检项目合格。	
668	GX-B1539/22-Y-23176	2023年8月16日	所检项目合格。	

669	GX-B1539/22-Y-23177	2023年8月16日	所检项目合格。	 <p>A photograph of a yellow Komatsu wheel loader parked on a dirt surface. Two workers wearing high-visibility vests and hard hats are standing next to the machine. The background shows a clear blue sky with some clouds and a distant horizon. A yellow timestamp '2023/8/16' is visible in the bottom right corner of the image.</p>
670	GX-B1385/21-Y-23080	2023年8月16日	所检项目合格。	 <p>A photograph of a worker wearing a red hard hat and a light blue uniform. The worker is holding a handheld device, possibly a scanner or a data collector, and is looking at it. The background is an industrial setting with metal structures and a red wall. A yellow timestamp '2023/6/8' is visible in the bottom right corner of the image.</p>

671	GX-B1328/20-Y-23086	2023年8月15日	本次共检绝缘手套28只，28只绝缘手套合格。	
672	GX-B1328/20-Y-23087	2023年8月15日	本次共检绝缘鞋26只，26只绝缘鞋合格。	

673	GX-B1328/20-Y-23088	2023年8月15日	本次共检验电器5支，5支验电器合格。	
674	GX-B1328/20-Y-23089	2023年8月15日	本次共检便携式接地和接地短路装置2组，2组便携式接地和接地短路装置合格。	

675	GX-B1328/20-Y-23091	2023年8月15日	本次共检绝缘手套2只，2只绝缘手套所检项目合格。	
676	GX-B1328/20-Y-23092	2023年8月15日	本次共检绝缘鞋2只，2只绝缘鞋所检项目合格。	

677	GX-B1328/20-Y-23093	2023年8月15日	所检项目合格。	 A photograph showing a worker in a red hard hat and grey uniform kneeling on a concrete floor. The worker is holding a device, possibly a detector or scanner, and appears to be inspecting equipment. In the background, there is a yellow metal frame and some cables. A yellow timestamp '2023/8/15' is visible in the bottom right corner of the photo.
678	GX-B1521/20-Y-23443	2023年8月15日	所检项目合格。	 A photograph of a yellow CAT excavator at a construction site. The excavator is positioned on a dirt surface, and its arm is raised. In the background, there are other construction vehicles and structures. A yellow timestamp '2023/8/15' is visible in the bottom right corner of the photo.

679	GX-B1521/20-Y-23444	2023年8月15日	所检项目合格。	
680	GX-B1423/20-Y-234707	2023年8月11日	综合判定：合格	

681	GX-B1539/22-Y-23192	2023年8月11日	所检项目合格。	
682	GX-B1539/22-Y-23193	2023年8月11日	所检项目合格。	

683	GX-B1539/22-Y-23194	2023年8月11日	所检项目合格。	
-----	---------------------	------------	---------	---