





序号	报告编号	发布日期	结论	影像资料
173	GX-B1328/20-1-23066	2023/8/23	本次共检绝缘手套120只，120只绝缘手套所检项目合格。	
174	GX-B1328/20-1-23067	2023/8/23	本次共检绝缘鞋120只，120只绝缘鞋所检项目合格。	
175	GX-B1328/20-1-23076	2023/8/23	绝缘手套2只，2只绝缘手套所检项目合格。	

176	GX-B1328/20-1-23077	2023/8/23	本次共检绝缘鞋2只，2只绝缘鞋所检项目合格。	
177	GX-B1328/20-1-23078	2023/8/23	所检项目合格。	
178	GX-B1328/20-1-23079	2023/8/23	所检项目合格。	
179	GX-B1423/20-1-23422	2023. 8. 23	综合判定：合格	

180	GX-B1423/20-1-23423	2023. 8. 23	综合判定：合格			
181	GX-B1423/20-1-23424	2023. 8. 23	综合判定：合格			
182	GX-B1423/20-1-23425	2023. 8. 23	综合判定：合格			
183	GX-B1423/20-1-23426	2023. 8. 23	综合判定：合格			

184	GX-B1423/20-1-23427	2023. 8. 23	综合判定：合格	
185	GX-B1423/20-1-23428	2023. 8. 23	综合判定：合格	
186	GX-B1423/20-1-23429	2023. 8. 23	综合判定：合格	
187	GX-B1423/20-1-23430	2023. 8. 23	综合判定：合格	

188	GX-B1423/20-1-23431	2023. 8. 23	综合判定：合格	
189	GX-B1423/20-1-23432	2023. 8. 23	综合判定：合格	
190	GX-B1423/20-1-23433	2023. 8. 23	综合判定：合格	
191	GX-B1423/20-1-23434	2023. 8. 23	综合判定：合格	

192	GX-B1423/20-1-23435	2023. 8. 23	综合判定：合格	
193	GX-B1423/20-1-23436	2023. 8. 23	综合判定：合格	
194	GX-B1423/20-1-23437	2023. 8. 23	综合判定：合格	
195	GX-B1423/20-1-23438	2023. 8. 23	综合判定：合格	

196	GX-B1423/20-1-23439	2023. 8. 23	综合判定：合格	
197	GX-B1423/20-1-23440	2023. 8. 23	综合判定：合格	
198	GX-B1423/20-1-23441	2023. 8. 23	综合判定：合格	
199	GX-B1423/20-1-23442	2023. 8. 23	综合判定：合格	

200	GX-B1423/20-1-23443	2023. 8. 23	综合判定：合格	
201	GX-B1423/20-1-23444	2023. 8. 23	综合判定：合格	
202	GX-B1423/20-1-23445	2023. 8. 23	综合判定：合格	
203	GX-B1423/20-1-23446	2023. 8. 23	综合判定：合格	



204	GX-B1423/20-1-23395	2023/8/24	综合判定：合格	
205	GX-B1423/20-1-23396	2023/8/24	综合判定：合格	
206	GX-B1423/20-1-23397	2023/8/24	综合判定：合格	
207	GX-B1423/20-1-23398	2023/8/24	综合判定：合格	

208	GX-B1423/20-1-23399	2023/8/24	综合判定：合格	
209	GX-B1423/20-1-23400	2023/8/24	综合判定：合格	
210	GX-B1423/20-1-23401	2023/8/24	综合判定：合格	
211	GX-B1423/20-1-23402	2023/8/24	综合判定：合格	

212	GX-B1423/20-1-23403	2023/8/24	综合判定：合格	
213	GX-B1423/20-1-23404	2023/8/24	综合判定：合格	
214	GX-B1423/20-1-23405	2023/8/24	综合判定：合格	
215	GX-B1423/20-1-23406	2023/8/24	综合判定：合格	

216	GX-B1423/20-1-23407	2023/8/24	综合判定：合格			
217	GX-B1423/20-1-23408	2023/8/24	综合判定：合格			
218	GX-B1423/20-1-23409	2023/8/24	综合判定：合格			
219	GX-B1423/20-1-23410	2023/8/24	综合判定：合格			

220	GX-B1423/20-1-23411	2023/8/24	综合判定：合格		
221	GX-B1423/20-1-23412	2023/8/24	综合判定：合格		
222	GX-B1423/20-1-23413	2023/8/24	综合判定：合格		
223	GX-B1423/20-1-23414	2023/8/24	综合判定：合格		

224	GX-B1423/20-1-23415	2023/8/24	综合判定：合格	
225	GX-B1423/20-1-23416	2023/8/24	综合判定：合格	
226	GX-B1423/20-1-23417	2023/8/24	综合判定：合格	
227	GX-B1423/20-1-23418	2023/8/24	综合判定：合格	

228	GX-B1423/20-1-23419	2023/8/24	综合判定：合格	
229	GX-B1423/20-1-23420	2023/8/24	综合判定：合格	
230	GX-B1423/20-1-23421	2023/8/24	综合判定：合格	
231	GX-B1383/21-1-23013	2023. 8. 24	所检项目合格。	

232	GX-B1383/21-1-23014	2023. 8. 24	所检项目合格。	
233	GX-B1382/21-1-23028	2023/8/24	综合判定:合格。	
234	GX-B1310/21-1-23124	2023. 8. 25	符合标准要求	
235	GX-B1310/21-1-23125	2023. 8. 25	符合标准要求	



236	GX-B1310/21-1-23126	2023. 8. 25	符合标准要求	 2023/08/10
237	GX-B1310/21-1-23127	2023. 8. 25	符合标准要求	 2023/08/10
238	GX-B1310/21-1-23128	2023. 8. 25	符合标准要求	 2023/08/10
239	GX-B1427/21-1-23125	2023. 8. 25	符合标准要求	 2023/08/10

240	GX-B1423/20-1-23573	2023/8/26	综合判定：合格	 A yellow MTBM truck with the number 26 on its side. Two workers in safety gear are standing in front of the truck. The date 2023.08.26 is visible in the bottom right corner of the photo.
241	GX-B1423/20-1-23574	2023/8/26	综合判定：合格	 A yellow MTBM truck with the number 27 on its side. Two workers in safety gear are standing in front of the truck. The date 2023.08.26 is visible in the bottom right corner of the photo.
242	GX-B1423/20-1-23575	2023/8/26	综合判定：合格	 A yellow MTBM truck with the number 22 on its side. Two workers in safety gear are standing in front of the truck. The date 2023.08.26 is visible in the bottom right corner of the photo.
243	GX-B1423/20-1-23576	2023/8/26	综合判定：合格	 A yellow MTBM truck. Two workers in safety gear are standing in front of the truck. The date 2023.08.26 is visible in the bottom right corner of the photo.

244	GX-B1423/20-1-23577	2023/8/26	综合判定：合格	 A photograph showing two workers wearing hard hats and safety vests standing in front of a yellow truck. The truck has the number '10' on its side. The date '2023/08/26' is visible in the bottom right corner of the image.
245	GX-B1423/20-1-23578	2023/8/26	综合判定：合格	 A photograph showing two workers wearing hard hats and safety vests standing in front of a yellow truck. The truck has the number '13' on its side. The date '2023/08/26' is visible in the bottom right corner of the image.
246	GX-B1300/20-1-23013	2023/8/28	综合判定：合格	 A photograph showing a worker wearing a red hard hat and safety glasses operating a green machine. The date '2023/07/08' is visible in the bottom right corner of the image.