


序号	报告编号	发布日期	结论	影像资料
31	GX-B1600/21-F-23018	2023. 9. 7	可不注水煤层	
32	GX-B1489/21-F- 23083	2023. 9. 13	所检项目合格	
33	GX-B1377/22-F-23264	2023. 9. 13	所检项目合格	

34	GX-B1377/22-F-23265	2023. 9. 13	所检项目合格	
35	GX-B1377/22-F-23266	2023. 9. 13	所检项目合格	
36	GX-B1377/22-F-23267	2023. 9. 13	所检项目合格	

37	GX-B1378/22-F-23196	2023. 9. 13	所检项目合格	
38	GX-B1377/22-F-23272	2023. 9. 13	所检项目合格	
39	GX-B1378/22-F-23197~F-23201	2023. 9. 18	所检项目合格	