

序号	报告编号	发布日期	结论	影像资料
200	GX-B1521/20-Y-23573	2023年10月7日	所检项目合格。	
201	GX-B1521/20-Y-23574	2023年10月7日	所检项目合格。	

202	GX-B1521/20-Y-23575	2023年10月7日	所检项目合格。	
203	GX-B1521/20-Y-23576	2023年10月7日	所检项目合格。	

204	GX-B1521/20-Y-23577	2023年10月7日	所检项目合格。	
205	GX-B1521/20-Y-23578	2023年10月7日	所检项目合格。	

206	GX-B1521/20-Y-23579	2023年10月7日	所检项目合格。	
207	GX-B1521/20-Y-23580	2023年10月7日	所检项目合格。	

208	GX-B1521/20-Y-23581	2023年10月7日	所检项目合格。	
209	GX-B1521/20-Y-23582	2023年10月7日	所检项目合格。	

210	GX-B1521/20-Y-23583	2023年10月7日	所检项目合格。	
211	GX-B1521/20-Y-23584	2023年10月7日	所检项目合格。	

212	GX-B1521/20-Y-23585	2023年10月7日	所检项目合格。	
213	GX-B1521/20-Y-23586	2023年10月7日	所检项目合格。	

214	GX-B1521/20-Y-23587	2023年10月7日	所检项目合格。	
215	GX-B1521/20-Y-23588	2023年10月7日	所检项目合格。	

216	GX-B1521/20-Y-23589	2023年10月7日	所检项目合格。	
217	GX-B1521/20-Y-23590	2023年10月7日	所检项目合格。	

218	GX-B1521/20-Y-23591	2023年10月7日	所检项目合格。	
219	GX-B1521/20-Y-23592	2023年10月7日	所检项目合格。	

220	GX-B1521/20-Y-23593	2023年10月7日	所检项目合格。	
221	GX-B1521/20-Y-23563	2023年10月8日	所检项目合格。	

222	GX-B1521/20-Y-23564	2023年10月8日	所检项目合格。	
223	GX-B1521/20-Y-23565	2023年10月8日	所检项目合格。	

224	GX-B1521/20-Y-23566	2023年10月8日	所检项目合格。	
225	GX-B1521/20-Y-23567	2023年10月8日	所检项目合格。	

226	GX-B1521/20-Y-23568	2023年10月8日	所检项目合格。	
227	GX-B1521/20-Y-23569	2023年10月8日	所检项目合格。	

228	GX-B1521/20-Y-23570	2023年10月8日	所检项目合格。	
229	GX-B1521/20-Y-23571	2023年10月8日	所检项目合格。	

230	GX-B1521/20-Y-23572	2023年10月8日	所检项目合格。	
231	GX-B1417/22-Y-23096	2023年10月8日	综合判定：合格	

232	GX-B1417/22-Y-23097	2023年10月8日	综合判定：合格	
233	GX-B1417/22-Y-23098	2023年10月8日	综合判定：合格	

234	GX-B1417/22-Y-23099	2023年10月8日	综合判定：合格	
235	GX-B1417/22-Y-23100	2023年10月8日	综合判定：合格	

236	GX-B1559/22-Y-23018	2023年10月8日	所检项目合格。	
237	GX-B1495/20-Y-231638	2023年10月9日	所检项目合格。	

238	GX-B1423/20-Y-235327	2023年10月11日	综合判定：合格	
239	GX-B1423/20-Y-235328	2023年10月11日	综合判定：合格	

240	GX-B1423/20-Y-235329	2023年10月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/8/10' is visible in the bottom right corner of the photo.
241	GX-B1423/20-Y-235330	2023年10月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/9/16' is visible in the bottom right corner of the photo.

242	GX-B1423/20-Y-235331	2023年10月11日	综合判定：合格	 A photograph of a yellow dump truck parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck has the number '235331' on its side. A date stamp '2023/9/16' is visible in the bottom right corner of the photo.
243	GX-B1423/20-Y-235332	2023年10月11日	综合判定：合格	 A photograph of a yellow dump truck parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck has the number '235332' on its side. A date stamp '2023/9/16' is visible in the bottom right corner of the photo.

244	GX-B1423/20-Y-235333	2023年10月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two workers in high-visibility vests are standing next to the truck. The truck has "HYUNDAI" and "24000" visible on its side. A date stamp "2023/9/16" is in the bottom right corner.
245	GX-B1423/20-Y-235334	2023年10月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two workers in high-visibility vests are standing next to the truck. The truck has "HYUNDAI" and "24000" visible on its side. A date stamp "2023/9/16" is in the bottom right corner.

246	GX-B1423/20-Y-235335	2023年10月11日	综合判定：合格	 <p>A yellow dump truck is parked on a dirt surface under a clear blue sky. Two workers in safety gear are standing near the front of the truck. The license plate on the side of the truck reads 'GX-B1423'. A yellow timestamp '2023/9/16' is visible in the bottom right corner of the photo.</p>
247	GX-B1423/20-Y-235336	2023年10月11日	综合判定：合格	 <p>A yellow dump truck is parked on a dirt surface under a clear blue sky. Two workers in safety gear are standing near the front of the truck. The license plate on the side of the truck reads 'GX-B1423'. A yellow timestamp '2023/9/16' is visible in the bottom right corner of the photo.</p>

248	GX-B1423/20-Y-235337	2023年10月11日	综合判定：合格	 A yellow dump truck with license plate GX-B1423/20-Y-235337 is shown in a desert-like environment. Two people are standing in front of the truck. The date 2023/9/16 is visible in the bottom right corner of the photo.
249	GX-B1423/20-Y-235338	2023年10月11日	综合判定：合格	 A yellow dump truck with license plate GX-B1423/20-Y-235338 is shown in a desert-like environment. Two people are standing in front of the truck. The date 2023/9/16 is visible in the bottom right corner of the photo.

250	GX-B1423/20-Y-235339	2023年10月11日	综合判定：合格	 A yellow dump truck is shown from a side-rear perspective. Two people are standing in front of the truck. The license plate reads 'GX-B1423'. The date '2023/9/16' is visible in the bottom right corner of the photo.
251	GX-B1423/20-Y-235340	2023年10月11日	综合判定：合格	 A yellow dump truck is shown from a side-rear perspective. Two people are standing in front of the truck. The license plate reads 'GX-B1423'. The date '2023/9/16' is visible in the bottom right corner of the photo.

252	GX-B1423/20-Y-235341	2023年10月11日	综合判定：合格	
253	GX-B1423/20-Y-235342	2023年10月11日	综合判定：合格	

254	GX-B1423/20-Y-235343	2023年10月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. A person in a blue uniform and a high-visibility vest is standing next to the truck, inspecting it. The truck has a license plate that reads "桂A1423". A yellow timestamp "2023/9/16" is visible in the bottom right corner of the photo.
255	GX-B1423/20-Y-235344	2023年10月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. A person in a blue uniform and a high-visibility vest is standing next to the truck, inspecting it. The truck has a license plate that reads "桂A1423". A yellow timestamp "2023/9/16" is visible in the bottom right corner of the photo.

256	GX-B1423/20-Y-235345	2023年10月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. The truck is viewed from a side-rear angle. A person in a blue uniform is standing near the front of the truck. A bright light source, likely the sun, is visible in the upper left corner, creating a lens flare. A yellow date stamp '2023/9/16' is located in the bottom right corner of the image.
257	GX-B1423/20-Y-235346	2023年10月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. The truck is viewed from a side-rear angle. A person in a blue uniform and a person in a yellow safety vest are standing near the front of the truck. A bright light source, likely the sun, is visible in the upper left corner, creating a lens flare. A yellow date stamp '2023/9/16' is located in the bottom right corner of the image.

258	GX-B1423/20-Y-235347	2023年10月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two people are standing near the front of the truck. The license plate on the side of the truck reads "GX-B1423". A yellow timestamp "2023/9/17" is visible in the bottom right corner of the image.
259	GX-B1423/20-Y-235348	2023年10月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two people are standing near the front of the truck. The license plate on the side of the truck reads "GX-B1423". A yellow timestamp "2023/9/17" is visible in the bottom right corner of the image.

260	GX-B1423/20-Y-235349	2023年10月11日	综合判定：合格	 A photograph of a yellow dump truck parked on a dirt surface. Two people are standing near the front of the truck. The truck has 'HW4175' written on its side. A date stamp '2023/9/17' is visible in the bottom right corner of the photo.
261	GX-B1423/20-Y-235350	2023年10月11日	综合判定：合格	 A photograph of a yellow dump truck parked on a dirt surface. Two people are standing near the front of the truck. The truck has 'HW4175' written on its side. A date stamp '2023/9/17' is visible in the bottom right corner of the photo.

262	GX-B1423/20-Y-235351	2023年10月11日	综合判定：合格	 A yellow dump truck is shown from a side-rear perspective. Two people are standing near the front of the truck. The truck has a license plate that reads "桂A14232". The date "2023/9/17" is printed in the bottom right corner of the photo.
263	GX-B1423/20-Y-235352	2023年10月11日	综合判定：合格	 A yellow dump truck is shown from a side-rear perspective, similar to the first photo. Two people are standing near the front of the truck. The truck has a license plate that reads "桂A14232". The date "2023/9/17" is printed in the bottom right corner of the photo.

264	GX-B1423/20-Y-235353	2023年10月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two people in safety gear are standing near the front of the truck. A date stamp '2023/9/17' is visible in the bottom right corner of the photo.
265	GX-B1423/20-Y-235354	2023年10月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two people in safety gear are standing near the front of the truck. A date stamp '2023/9/17' is visible in the bottom right corner of the photo.

266	GX-B1423/20-Y-235355	2023年10月11日	综合判定：合格	
267	GX-B1423/20-Y-235356	2023年10月11日	综合判定：合格	

268	GX-B1423/20-Y-235357	2023年10月11日	综合判定：合格	
269	GX-B1423/20-Y-235358	2023年10月11日	综合判定：合格	

270	GX-B1423/20-Y-235359	2023年10月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two workers in safety gear are standing near the front of the truck. The truck has "KIMCHI" written on its side. A yellow timestamp "2023/9/17" is visible in the bottom right corner of the image.
271	GX-B1423/20-Y-235360	2023年10月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two workers in safety gear are standing near the front of the truck. The truck has "KIMCHI" written on its side. A yellow timestamp "2023/9/17" is visible in the bottom right corner of the image.

272	GX-B1423/20-Y-235361	2023年10月11日	综合判定：合格	 A yellow dump truck is parked on a sandy surface under a clear blue sky. The truck's bed is raised. Two people are standing near the front of the truck. The license plate area displays 'GX-B1423'. A yellow timestamp '2023/9/17' is visible in the bottom right corner of the image.
273	GX-B1423/20-Y-235362	2023年10月11日	综合判定：合格	 A yellow dump truck is parked on a sandy surface under a clear blue sky. The truck's bed is raised. Two people are standing near the front of the truck. The license plate area displays 'GX-B1423'. A yellow timestamp '2023/9/17' is visible in the bottom right corner of the image.

274	GX-B1423/20-Y-235363	2023年10月11日	综合判定：合格	 <p>A yellow Hino dump truck is shown from a rear three-quarter view. The license plate reads 'GX-B1423'. Two people are standing near the rear of the truck. The date '2023/9/17' is visible in the bottom right corner of the photo.</p>
275	GX-B1423/20-Y-235364	2023年10月11日	综合判定：合格	 <p>A yellow Hino dump truck is shown from a rear three-quarter view. The license plate reads 'GX-B1423'. Two people are standing near the rear of the truck. The date '2023/9/17' is visible in the bottom right corner of the photo.</p>

276	GX-B1423/20-Y-235365	2023年10月11日	综合判定：合格	
277	GX-B1423/20-Y-235366	2023年10月11日	综合判定：合格	

278	GX-B1329/21-Y-23271	2023年10月11日	所检项目合格。	
279	GX-B1328/20-Y-23136	2023年10月12日	本次共检绝缘鞋 12只，12只绝缘 鞋合格。	

280	GX-B1517/20-Y-23025	2023年10月12日	综合判定：合格。 。	
281	GX-B1517/20-Y-23026	2023年10月12日	综合判定：合格。 。	

282	GX-B1321/20-Y-23616~23621	2023年10月12日	本次共检验电力电缆6条，6条电力电缆所检项目合格。	 A photograph showing a worker in a red safety helmet and orange protective gloves working on a piece of electrical equipment, possibly a switchgear or control panel. The worker is wearing a light-colored long-sleeved shirt and dark pants. The equipment is mounted on a wall or panel. A yellow timestamp '2023/9/27' is visible in the bottom right corner of the photo.
283	GX-B1328/20-Y-23134	2023年10月12日	本次共检绝缘手套18只，18只绝缘手套合格。	 A photograph showing a worker in a red safety helmet and a blue long-sleeved shirt working on a piece of equipment outdoors. The worker is kneeling on a concrete surface. There are various tools and equipment scattered around, including a blue bucket and a red fire extinguisher. A yellow timestamp '2023/9/27' is visible in the bottom right corner of the photo.

284	GX-B1328/20-Y-23135	2023年10月11日	本次共检绝缘鞋 10只，10只绝缘 鞋合格。	
-----	---------------------	-------------	------------------------------	---