




序号	报告编号	发布日期	结论	影像资料
285	GX-B1539/22-Y-23233	2023年10月13日	所检项目合格。	 A yellow wheel loader is parked on a dirt surface under a clear blue sky. Two people are standing in front of the loader. A yellow date stamp '2023/10/13' is visible in the bottom right corner of the photo.
286	GX-B1539/22-Y-23234	2023年10月13日	所检项目合格。	 A yellow wheel loader is parked on a dirt surface under a clear blue sky. Two people are standing in front of the loader. A yellow date stamp '2023/10/13' is visible in the bottom right corner of the photo.

287	GX-B1539/22-Y-23235	2023年10月13日	所检项目合格。	 A yellow wheel loader is parked on a dirt surface under a clear blue sky. Two people are standing in front of the loader. The loader has a license plate that reads "甘A H4003". A yellow timestamp "2023/9/18" is visible in the bottom right corner of the photo.
288	GX-B1521/20-Y-23555	2023年10月13日	所检项目合格。	 A yellow tracked excavator is parked on a dirt surface under a clear blue sky. A person is standing next to the excavator. The excavator has a license plate that reads "甘A H4003". A yellow timestamp "2023/9/18" is visible in the bottom right corner of the photo.

289	GX-B1521/20-Y-23556	2023年10月13日	所检项目合格。	 A yellow tracked excavator is shown in a desert environment under a clear blue sky. A person in a white uniform stands next to the machine for scale. The excavator's arm is raised. A yellow timestamp '2023/9/18' is visible in the bottom right corner of the photo.
290	GX-B1521/20-Y-23557	2023年10月13日	所检项目合格。	 A yellow tracked excavator is shown in a desert environment under a clear blue sky. A person in a white uniform stands next to the machine for scale. The excavator's arm is raised. A yellow timestamp '2023/9/18' is visible in the bottom right corner of the photo.

291	GX-B1521/20-Y-23558	2023年10月13日	所检项目合格。	
292	GX-B1521/20-Y-23559	2023年10月13日	所检项目合格。	

293	GX-B1521/20-Y-23560	2023年10月13日	所检项目合格。	 A yellow excavator is shown in a sandy, open area under a clear blue sky. The excavator's arm is raised, and a person is standing nearby. A yellow timestamp '2023/9/18' is visible in the bottom right corner of the photo.
294	GX-B1521/20-Y-23561	2023年10月13日	所检项目合格。	 A yellow excavator is shown in a sandy, open area under a clear blue sky. The excavator's arm is raised, and a person is standing nearby. A yellow timestamp '2023/9/18' is visible in the bottom right corner of the photo.

295	GX-B1521/20-Y-23562	2023年10月13日	所检项目合格。	
296	GX-B1522/20-Y-23142	2023年10月12日	所检项目合格。	

297	GX-B1522/20-Y-23143	2023年10月12日	所检项目合格。	
298	GX-B1423/20-Y-235564	2023年10月12日	综合判定：合格	

299	GX-B1423/20-Y-235565	2023年10月12日	综合判定：合格	
300	GX-B1423/20-Y-235566	2023年10月12日	综合判定：合格	

301	GX-B1423/20-Y-235567	2023年10月12日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck has the number '167' on its side. A yellow timestamp '2023/9/30' is visible in the bottom right corner of the photo.
302	GX-B1423/20-Y-235568	2023年10月12日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a blue sky with some clouds. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck has the number '167' on its side. A yellow timestamp '2023/9/30' is visible in the bottom right corner of the photo.

303	GX-B1423/20-Y-235569	2023年10月12日	综合判定：合格	
304	GX-B1423/20-Y-235570	2023年10月12日	综合判定：合格	

305	GX-B1423/20-Y-235571	2023年10月12日	综合判定：合格	
306	GX-B1423/20-Y-235572	2023年10月12日	综合判定：合格	

307	GX-B1423/20-Y-235573	2023年10月12日	综合判定：合格	
308	GX-B1423/20-Y-235574	2023年10月12日	综合判定：合格	

309	GX-B1423/20-Y-235575	2023年10月12日	综合判定：合格	
310	GX-B1423/20-Y-235576	2023年10月12日	综合判定：合格	

311	GX-B1423/20-Y-235577	2023年10月12日	综合判定：合格	
312	GX-B1423/20-Y-235578	2023年10月12日	综合判定：合格	

313	GX-B1423/20-Y-235579	2023年10月12日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck has 'K-103' on the front. A date stamp '2023/9/30' is visible in the bottom right corner of the image.
314	GX-B1423/20-Y-235580	2023年10月12日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. A date stamp '2023/10/1' is visible in the bottom right corner of the image.

315	GX-B1423/20-Y-235581	2023年10月12日	综合判定：合格	
316	GX-B1423/20-Y-235582	2023年10月12日	综合判定：合格	

317	GX-B1423/20-Y-235583	2023年10月12日	综合判定：合格	 A yellow dump truck is shown from a side profile with its bed in the down position. A person in a high-visibility vest stands to the left of the truck. The background is a dry, hilly landscape under a blue sky with scattered clouds. A yellow timestamp '2023/10/1' is visible in the bottom right corner of the photo.
318	GX-B1423/20-Y-235584	2023年10月12日	综合判定：合格	 A yellow dump truck is shown from a side profile with its bed in the up position. A person in a high-visibility vest stands to the left of the truck. The background is a dry, hilly landscape under a blue sky with scattered clouds. A yellow timestamp '2023/10/1' is visible in the bottom right corner of the photo.

319	GX-B1423/20-Y-235585	2023年10月12日	综合判定：合格	
320	GX-B1423/20-Y-235586	2023年10月12日	综合判定：合格	

321	GX-B1423/20-Y-235587	2023年10月12日	综合判定：合格	
322	GX-B1423/20-Y-235588	2023年10月12日	综合判定：合格	

323	GX-B1423/20-Y-235589	2023年10月12日	综合判定：合格	
324	GX-B1423/20-Y-235590	2023年10月12日	综合判定：合格	

325	GX-B1423/20-Y-235591	2023年10月12日	综合判定：合格	
326	GX-B1423/20-Y-235592	2023年10月12日	综合判定：合格	

327	GX-B1423/20-Y-235593	2023年10月12日	综合判定：合格	 A yellow MT983 dump truck is parked on a dirt surface. The truck has the number '153' on its side and 'MT983' on the front. Two workers in safety gear are standing in front of the truck. A date stamp '2023/10/1' is visible in the bottom right corner of the image.
328	GX-B1423/20-Y-235594	2023年10月12日	综合判定：合格	 A yellow MT983 dump truck is parked on a dirt surface. The truck has the number '152' on its side and 'MT983' on the front. Two workers in safety gear are standing in front of the truck. A date stamp '2023/10/1' is visible in the bottom right corner of the image.

329	GX-B1423/20-Y-235595	2023年10月12日	综合判定：合格	
330	GX-B1423/20-Y-235596	2023年10月12日	综合判定：合格	

331	GX-B1557/22-Y-23040	2023年10月13日	所检项目合格。	
332	GX-B1563/21-Y-23033	2023年10月13日	所检项目合格。	

333	GX-B1563/21-Y-23034	2023年10月13日	所检项目合格。	
-----	---------------------	-------------	---------	---