





| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|----------------------|------------|--------|--|
| 87 | GX-B1361/22-A-231014 | 2023/10/10 | 所检项目合格 |  A photograph showing a worker in a light-colored short-sleeved shirt operating a lathe machine in a workshop. The machine is mounted on a wooden workbench. The worker is focused on the task. In the background, another person is partially visible. The room has white walls and yellow curtains. A yellow timestamp '2023/9/28' is visible in the bottom right corner of the image. |
| 88 | GX-B1361/22-A-231015 | 2023/10/10 | 所检项目合格 |  A photograph showing a worker in a light-colored short-sleeved shirt operating a lathe machine in a workshop. The machine is mounted on a wooden workbench. The worker is focused on the task. In the background, another person is partially visible. The room has white walls and yellow curtains. A yellow timestamp '2023/9/28' is visible in the bottom right corner of the image. |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|----------------------|------------|--------|--|
| 89 | GX-B1361/22-A-231016 | 2023/10/10 | 所检项目合格 |  |
| 90 | GX-B1361/22-A-231017 | 2023/10/10 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|----------------------|------------|--------|--|
| 91 | GX-B1361/22-A-231037 | 2023/10/13 | 所检项目合格 |  |
| 92 | GX-B1361/22-A-231038 | 2023/10/13 | 所检项目合格 |  |



| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|---------------------|------------|--------|--|
| 93 | GX-B1361/22-A-23998 | 2023/10/15 | 所检项目合格 |  |
| 94 | GX-B1361/22-A-23999 | 2023/10/15 | 所检项目合格 |  |



| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|----------------------|------------|--------|--|
| 95 | GX-B1361/22-A-231000 | 2023/10/15 | 所检项目合格 |  |
| 96 | GX-B1361/22-A-231001 | 2023/10/15 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|----------------------|------------|--------|--|
| 97 | GX-B1361/22-A-231002 | 2023/10/15 | 所检项目合格 |  |
| 98 | GX-B1361/22-A-231003 | 2023/10/15 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|--------|--|
| 99 | GX-B1361/22-A-231004 | 2023/10/15 | 所检项目合格 |  |
| 100 | GX-B1361/22-A-231005 | 2023/10/15 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|--------|--|
| 101 | GX-B1361/22-A-231028 | 2023/10/15 | 所检项目合格 |  |
| 102 | GX-B1361/22-A-231029 | 2023/10/15 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 | |
|-----|----------------------|------------|--------|------|--|
| 103 | GX-B1361/22-A-231030 | 2023/10/15 | 所检项目合格 | |  |
| 104 | GX-B1361/22-A-231039 | 2023/10/15 | 所检项目合格 | |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|--------|--|
| 105 | GX-B1361/22-A-231040 | 2023/10/15 | 不合格 |  |
| 106 | GX-B1361/22-A-231041 | 2023/10/16 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|--------|--|
| 107 | GX-B1361/22-A-231042 | 2023/10/16 | 所检项目合格 |  |
| 108 | GX-B1361/22-A-231043 | 2023/10/16 | 合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|--------|--|
| 109 | GX-B1361/22-A-231044 | 2023/10/16 | 所检项目合格 |  |
| 110 | GX-B1361/22-A-231045 | 2023/10/16 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|--------|--|
| 111 | GX-B1361/22-A-231046 | 2023/10/16 | 所检项目合格 |  |
| 112 | GX-B1361/22-A-231047 | 2023/10/16 | 不合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|--------|--|
| 113 | GX-B1361/22-A-231050 | 2023/10/16 | 所检项目合格 |  |
| 114 | GX-B1361/22-A-231080 | 2023/10/16 | 合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|----|--|
| 115 | GX-B1361/22-A-231081 | 2023/10/16 | 合格 |  |
| 116 | GX-B1361/22-A-231082 | 2023/10/16 | 合格 |  |


| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|----|--|
| 117 | GX-B1361/22-A-231083 | 2023/10/16 | 合格 |  |
| 118 | GX-B1361/22-A-231084 | 2023/10/16 | 合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|----|--|
| 119 | GX-B1361/22-A-231085 | 2023/10/16 | 合格 |  |
| 120 | GX-B1361/22-A-231086 | 2023/10/16 | 合格 |  |


| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|----|--|
| 121 | GX-B1362/20-A-23371 | 2023/10/18 | 合格 |  |
| 122 | GX-B1362/20-A-23372 | 2023/10/18 | 合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|--|
| 123 | GX-B1362/20-A-23376 | 2023/10/18 | 所检项目合格 |  |
| 124 | GX-B1362/20-A-23377 | 2023/10/18 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|--------|--|
| 125 | GX-B1361/22-A-231048 | 2023/10/16 | 所检项目合格 |  |
| 126 | GX-B1361/22-A-231049 | 2023/10/16 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|--------|--|
| 127 | GX-B1361/22-A-231051 | 2023/10/17 | 所检项目合格 |  |
| 128 | GX-B1361/22-A-231052 | 2023/10/17 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|--------|--|
| 129 | GX-B1361/22-A-231053 | 2023/10/17 | 所检项目合格 |  |
| 130 | GX-B1361/22-A-231054 | 2023/10/17 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|--------|---|
| 131 | GX-B1361/22-A-231055 | 2023/10/17 | 所检项目合格 |  A photograph showing two men in light-colored work shirts working in a workshop. They are positioned around a large industrial machine, possibly a lathe or mill. The man on the right is looking down at the machine, while the man on the left is looking towards the camera. The room has white walls and a window with yellow curtains. A date stamp '2023/10/8' is visible in the bottom right corner of the image. |
| 132 | GX-B1361/22-A-231056 | 2023/10/17 | 所检项目合格 |  A photograph showing two men in light-colored work shirts working in a workshop. They are positioned around a large industrial machine, possibly a lathe or mill. The man on the right is looking down at the machine, while the man on the left is looking towards the camera. The room has white walls and a window with yellow curtains. A date stamp '2023/10/9' is visible in the bottom right corner of the image. |


| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|--------|--|
| 133 | GX-B1361/22-A-231057 | 2023/10/17 | 所检项目合格 |  |
| 134 | GX-B1361/22-A-231058 | 2023/10/17 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|--------|--|
| 135 | GX-B1361/22-A-231059 | 2023/10/17 | 所检项目合格 |  |
| 136 | GX-B1361/22-A-231060 | 2023/10/17 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|--------|--|
| 137 | GX-B1361/22-A-231061 | 2023/10/17 | 所检项目合格 |  |
| 138 | GX-B1361/22-A-231062 | 2023/10/17 | 所检项目合格 |  |



| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|----|--|
| 139 | GX-B1361/22-A-231063 | 2023/10/18 | 合格 |  |
| 140 | GX-B1361/22-A-231064 | 2023/10/18 | 合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|----|--|
| 141 | GX-B1361/22-A-231065 | 2023/10/18 | 合格 |  |
| 142 | GX-B1361/22-A-231066 | 2023/10/18 | 合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|----|---|
| 143 | GX-B1361/22-A-231067 | 2023/10/18 | 合格 |  A photograph showing a male worker in a light-colored short-sleeved shirt operating a lathe machine in a workshop. The worker is focused on his task. In the background, another person is partially visible. The room has yellow curtains and a window. A yellow timestamp '2023/10/11' is visible in the bottom right corner of the image. |
| 144 | GX-B1361/22-A-231068 | 2023/10/18 | 合格 |  A photograph showing two male workers in light-colored short-sleeved shirts operating a machine in a workshop. One worker is in the foreground, wearing white gloves and looking at the machine. The other worker is in the background. The room has yellow curtains and a window. A yellow timestamp '2023/10/11' is visible in the bottom right corner of the image. |


| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|--------|--|
| 145 | GX-B1361/22-A-231069 | 2023/10/18 | 合格 |  |
| 146 | GX-B1361/22-A-231070 | 2023/10/18 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|--------|--|
| 147 | GX-B1361/22-A-231071 | 2023/10/18 | 所检项目合格 |  |
| 148 | GX-B1361/22-A-231072 | 2023/10/18 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|--------|--|
| 149 | GX-B1361/22-A-231073 | 2023/10/18 | 所检项目合格 |  |
| 150 | GX-B1361/22-A-231074 | 2023/10/19 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|--------|--|
| 151 | GX-B1361/22-A-231075 | 2023/10/19 | 所检项目合格 |  |
| 152 | GX-B1361/22-A-231076 | 2023/10/19 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|--------|--|
| 153 | GX-B1361/22-A-231077 | 2023/10/19 | 所检项目合格 |  |
| 154 | GX-B1361/22-A-231078 | 2023/10/19 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|------------|--------|---|
| 155 | GX-B1361/22-A-231079 | 2023/10/19 | 所检项目合格 |  |