

序号	报告编号	发布日期	结论	影像资料
44	GX-B1495/20-5-231809~231810	2023/10/23	本次共检高压开关柜2台，2台高压开关柜所检项目合格。	
45	GX-B1310/21-5-23256	2023/10/23	符合标准要求。	
46	GX-B1428/21-5-23036	2023/10/23	无缺陷迹痕显示。	

47	GX-B1310/21-5-23255	2023/10/23	符合标准要求。		
48	GX-B1428/21-5-23035	2023/10/23	无缺陷迹痕显示。		
49	GX-B1329/21-5-23175~23189	2023/10/23	本次共检氧化锌避雷器15组，15组氧化锌避雷器所检项目合格。 。		

50	GX-B1310/21-5-23246	2023. 10. 23	符合标准要求。	
51	GX-B1310/21-5-23247	2023. 10. 23	符合标准要求。	
52	GX-B1310/21-5-23248	2023. 10. 23	符合标准要求。	

53	GX-B1310/21-5-23249	2023. 10. 23	符合标准要求。			
54	GX-B1310/21-5-23250	2023. 10. 23	符合标准要求。			
55	GX-B1310/21-5-23251	2023. 10. 23	符合标准要求。			

56	GX-B1328/20-5-23170	2023. 10. 24	本次共检绝缘手套88只，88只绝缘手套合格。	
57	GX-B1328/20-5-23171	2023. 10. 24	本次共检绝缘鞋84只，84只绝缘鞋合格。	
58	GX-B1424/20-5-23047	2023. 10. 24	依据NB/T 10176-2019单轨吊车所检项目合格。	

59	GX-B1495/20-5-231789~231808	2023/10/26	本次共检高压开关柜20台，20台高压开关柜所检项目合格。		
60	GX-B1310/21-5-23272	2023. 10. 27	符合标准要求。		
61	GX-B1310/21-5-23273	2023. 10. 27	符合标准要求。		

62	GX-B1300/23-5-23039	2023. 10. 27	合格	
63	GX-B1383/21-5-23014	2023. 10. 27	合格	
64	GX-B1383/21-5-23015	2023. 10. 27	合格	

65	GX-B1310/21-5-23260	2023. 10. 30	符合标准要求。	
66	GX-B1310/21-5-23261	2023. 10. 30	符合标准要求。	
67	GX-B1310/21-5-23262	2023. 10. 30	符合标准要求。	

68	GX-B1310/21-5-23263	2023. 10. 30	符合标准要求。			
69	GX-B1310/21-5-23264	2023. 10. 30	符合标准要求。			
70	GX-B1310/21-5-23265	2023. 10. 30	符合标准要求。			

71	GX-B1310/21-5-23266	2023. 10. 30	符合标准要求。			
72	GX-B1310/21-5-23267	2023. 10. 30	符合标准要求。			
73	GX-B1310/21-5-23268	2023. 10. 30	符合标准要求。			

74	GX-B1310/21-5-23269	2023. 10. 30	符合标准要求。			
75	GX-B1310/21-5-23270	2023. 10. 30	符合标准要求。			
76	GX-B1310/21-5-23271	2023. 10. 30	符合标准要求。			

77	GX-B1350/21-5-23064	2023. 10. 30	<p>本次共检接地装置 2处, 2处接地装置所检 项目合格。</p>	
78	GX-B1352/21-5-23322~23325	2023. 10. 30	<p>本次共检矿用防爆低 压交流真空馈电开关4 台, 4台所检项目合格 。</p>	
79	GX-B1310/21-5-23274	2023. 10. 30	<p>符合标准要求。</p>	

80	GX-B1495/20-5-231860-231864	2023. 10. 30	本次共检高压开关柜5台，5台高压开关柜所检项目合格。	
81	GX-B1354/20-5-23017	2023. 10. 27	电网接地电容电流符合规定。	
82	GX-B1354/20-5-23018	2023. 10. 27	电网接地电容电流符合规定。	

83	GX-B11517/20-5-23028	2023. 10. 30	综合判定：合格。	
84	GX-B1328/20-5-23158	2023. 10. 30	本次共检绝缘手套10只，10只绝缘手套合格。	
85	GX-B1328/20-5-23159	2023. 10. 30	本次共检绝缘10只，10只绝缘鞋合格。	




86	GX-B1328/20-5-23160	2023. 10. 30	本次共检便携式接地和接地短路装置5套，5套便携式接地和接地短路装置合格。	
87	GX-B1328/20-5-23161	2023. 10. 30	本次共检验电器5套，5套验电器合格。	
88	GX-B1306/21-5-23086	2023. 10. 30	所检项目合格	

89	GX-B1306/21-5-23087	2023. 10. 30	所检项目合格	
90	GX-B1306/21-5-23088	2023. 10. 30	所检项目合格	
91	GX-B1306/21-5-23089	2023. 10. 30	所检项目合格	

92	GX-B1312/20-5-23538	2023. 10. 31	所检项目合格。	 A worker wearing a full white protective suit and a white helmet stands in a dark, possibly confined space. The worker is facing the camera. A red timestamp '2023.10.19' is visible in the bottom right corner of the photo.
93	GX-B1321/20-5-23920	2023. 10. 31	所检项目合格。	 A worker wearing a blue uniform and a red helmet is working in a dark environment. The worker is kneeling or sitting on the ground, surrounded by equipment. A red timestamp '2023.10.19' is visible in the bottom right corner of the photo.
94	GX-B1312/20-5-23537	2023. 10. 31	所检项目合格。	 A worker wearing a blue uniform and a red helmet is working in a dark environment. The worker is kneeling or sitting on the ground, surrounded by equipment. A red timestamp '2023.10.11' is visible in the bottom right corner of the photo.

95	GX-B1321/20-5-23919	2023. 10. 31	所检项目合格。	
96	GX-B1300/20-5-23038	2023. 10. 31	所检项目合格。	
97	GX-B1300/20-5-23035	2023. 10. 30	所检项目合格。	

98	GX-B1300/20-5-23036	2023/10/27	所检项目合格。	
99	GX-B1300/20-5-23037	2023/10/27	所检项目合格。	
100	GX-B1495/20-5-231789~231808	2023/10/26	本次共检高压开关柜20台，20台高压开关柜所检项目合格。	 

101	GX-B1499/21-5-23092	2023/10/28	除吨水百米电耗超限外，其余所检项目合格。	 A dark, dimly lit underground space, possibly a tunnel or shaft, with some equipment and structural elements visible. A yellow timestamp '2023/10/13' is in the bottom right corner.
102	GX-B1499/21-5-23093	2023/10/28	除吨水百米电耗超限外，其余所检项目合格。	 A dark, dimly lit underground space, similar to the first photo, showing more structural details and equipment. A yellow timestamp '2023/10/13' is in the bottom right corner.
103	GX-B1499/21-5-23094	2023/10/28	除吨水百米电耗超限外，其余所检项目合格。	 A dark, dimly lit underground space, showing a different view of the interior. A yellow timestamp '2023/10/13' is in the bottom right corner.

104	GX-B1499/21-5-23095	2023/10/28	除吨水百米电耗超限外，其余所检项目合格。	
105	GX-B1499/21-5-23096	2023/10/28	除吨水百米电耗超限外，其余所检项目合格。	