

序号	报告编号	发布日期	结论	影像资料
307	GX-B1362/20-A-23448	2023/11/23	所检项目合格	
308	GX-B1362/20-A-23449	2023/11/23	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
309	GX-B1362/20-A-23450	2023/11/23	所检项目合格	
310	GX-B1362/20-A-23451	2023/11/23	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
311	GX-B1362/20-A-23452	2023/11/23	所检项目合格	
312	GX-B1362/20-A-23453	2023/11/23	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
313	GX-B1362/20-A-23454	2023/11/23	所检项目合格	
314	GX-B1362/20-A-23455	2023/11/23	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
315	GX-B1362/20-A-23456	2023/11/23	所检项目合格	
316	GX-B1362/20-A-23457	2023/11/23	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
317	GX-B1362/20-A-23458	2023/11/23	所检项目合格	
318	GX-B1361/22-A-231163	2023/11/24	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
319	GX-B1361/22-A-231164	2023/11/24	所检项目合格	
320	GX-B1361/22-A-231165	2023/11/24	不合格	

序号	报告编号	发布日期	结论	影像资料
321	GX-B1361/22-A-231169	2023/11/24	所检项目合格	 A photograph showing a worker in a light-colored uniform operating a lathe machine in a workshop. The worker is focused on the task, and the machine is in operation. A date stamp '2023/11/7' is visible in the bottom right corner of the image.
322	GX-B1361/22-A-231170	2023/11/24	所检项目合格	 A photograph showing a worker in a light-colored uniform operating a lathe machine in a workshop. The worker is wearing gloves and is focused on the task. A date stamp '2023/11/7' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
323	GX-B1361/22-A-231171	2023/11/24	所检项目合格	
324	GX-B1361/22-A-231172	2023/11/24	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
325	GX-B1361/22-A-231173	2023/11/24	所检项目合格	
326	GX-B1361/22-A-231174	2023/11/24	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
327	GX-B1361/22-A-231175	2023/11/24	所检项目合格	
328	GX-B1361/22-A-231176	2023/11/24	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
329	GX-B1361/22-A-231177	2023/11/24	所检项目合格	
330	GX-B1361/22-A-231178	2023/11/24	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
331	GX-B1361/22-A-231179	2023/11/24	所检项目合格	
332	GX-B1361/22-A-231180	2023/11/24	所检项目合格	


序号	报告编号	发布日期	结论	影像资料
333	GX-B1361/22-A-231181	2023/11/24	所检项目合格	 A photograph showing two male workers in grey work uniforms operating a large industrial machine in a workshop. The worker on the right is wearing yellow gloves and is focused on a task. The worker on the left is looking towards the machine. The machine has a large metal tray on top. A yellow date stamp '2023/11/9' is visible in the bottom right corner of the image.
334	GX-B1361/22-A-231182	2023/11/24	所检项目合格	 A photograph showing two male workers in grey work uniforms operating a large industrial machine in a workshop. The worker on the right is wearing yellow gloves and is focused on a task. The worker on the left is looking towards the machine. The machine has a large metal tray on top. A yellow date stamp '2023/11/9' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
335	GX-B1361/22-A-231183	2023/11/24	所检项目合格	
336	GX-B1361/22-A-231219	2023/11/24	合格	

序号	报告编号	发布日期	结论	影像资料
337	GX-B1361/22-A-231220	2023/11/24	合格	
338	GX-B1361/22-A-231203	2023/11/30	合格	

序号	报告编号	发布日期	结论	影像资料
339	GX-B1361/22-A-231204	2023/11/30	合格	
340	GX-B1361/22-A-231212	2023/11/30	不合格	

序号	报告编号	发布日期	结论	影像资料
341	GX-B1361/22-A-231213	2023/11/30	不合格	
342	GX-B1361/22-A-231221	2023/11/30	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
343	GX-B1361/22-A-231222	2023/11/30	所检项目合格	
344	GX-B1361/22-A-231223	2023/11/30	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
345	GX-B1361/22-A-231255	2023/11/30	所检项目合格	
346	GX-B1361/22-A-231256	2023/11/30	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
347	GX-B1362/20-A-23459	2023/11/30	所检项目合格	