

序号	报告编号	发布日期	结论	影像资料
34	GX-B1428/21-P-23038	2023.12.1	无缺陷迹痕显示。	 A photograph showing a worker wearing a red safety helmet and a blue jacket, inspecting a structure. The worker is holding a flashlight, and the scene is dimly lit. A date stamp '2023.11.16' is visible in the bottom right corner of the image.
35	GX-B1428/21-P-23039	2023.12.1	无缺陷迹痕显示。	 A photograph showing a worker wearing a red safety helmet and a blue jacket, inspecting a structure. The worker is holding a flashlight, and the scene is dimly lit. A date stamp '2023.11.16' is visible in the bottom right corner of the image.

36	GX-B1310/21-P-23158	2023. 12. 1	符合标准要求。	
37	GX-B1310/21-P-23159	2023. 12. 1	符合标准要求。	
38	GX-B1539/22-P-23001	2023. 12. 5	所检项目合格。	

39	GX-B1539/22-P-23002	2023. 12. 5	所检项目合格。	
40	GX-B1539/22-P-23003	2023. 12. 5	所检项目合格。	
41	GX-B1559/22-P-23171	2023. 12. 5	所检项目合格	

42	GX-B1559/22-P-23172	2023. 12. 5	所检项目合格	
43	GX-B1417/22-P-231743	2023. 12. 5	综合判定：合格。	
44	GX-B1559/22-P-231738	2023. 12. 5	综合判定：合格	

45	GX-B1559/22-P-231739	2023. 12. 5	综合判定：合格	
46	GX-B1559/22-P-231740	2023. 12. 5	综合判定：合格	
47	GX-B1559/22-P-231741	2023. 12. 5	综合判定：合格	

48	GX-B1559/22-P-231742	2023. 12. 5	综合判定：合格	
49	GX-B1417/22-P-231750	2023. 12. 6	综合判定：合格。	
50	GX-B1417/22-P-231751	2023. 12. 6	综合判定：合格。	

51	GX-B1521/20-P-23001	2023. 12. 7	所检项目合格。	 <p>A yellow CAT 240 excavator is shown at a construction site. A worker in a red hard hat and grey jacket is standing to the left, looking at a clipboard. Another worker is visible in the background. The excavator's arm is raised. The date stamp in the bottom right corner of the photo is 2023.11.30.</p>
52	GX-B1521/20-P-23002	2023. 12. 7	所检项目合格。	 <p>A worker in a red hard hat and grey jacket is standing next to a yellow SINOBO 7 excavator. The excavator has "SINOBO 宏州中联" and "7" written on it. The date stamp in the bottom right corner of the photo is 2023.11.30.</p>
53	GX-B1521/20-P-23003	2023. 12. 7	所检项目合格。	 <p>A worker in a red hard hat and grey jacket is sitting in the operator's seat of an excavator, looking at a device. A red hard hat is in the foreground. The date stamp in the bottom right corner of the photo is 2023.11.30.</p>

54	GX-B1521/20-P-23004	2023. 12. 7	所检项目合格。	
55	GX-B1521/20-P-23005	2023. 12. 7	所检项目合格。	
56	GX-B1521/20-P-23006	2023. 12. 7	所检项目合格。	

57	GX-B1521/20-P-23007	2023. 12. 7	所检项目合格。	 A photograph showing a worker wearing a red hard hat and a brown jacket, standing next to a yellow excavator. The worker is looking at the excavator's arm and bucket. The background shows a construction site with a pile of rocks and a cloudy sky.
----	---------------------	-------------	---------	--