

序号	报告编号	发布日期	结论	影像资料
31	GX-B1378/22-F-23262	2023. 12. 18	所检项目合格	 A photograph showing two female technicians in a laboratory. They are wearing grey work jackets. One technician is wearing a face mask. They are standing next to a piece of scientific equipment, possibly a microscope or a specialized testing device. The background shows a clean laboratory environment with shelves and other equipment. A small timestamp '2023/12/18' is visible in the bottom right corner of the image.
32	GX-B1377/22-F-23307	2023. 12. 18	除击穿电压不合格外，其余所检项目合格	 A photograph showing two female technicians in a laboratory. They are wearing grey work jackets. One technician is wearing a face mask. They are standing next to a piece of scientific equipment, possibly a specialized testing device. The background shows a clean laboratory environment with shelves and other equipment. A small timestamp '2023/12/18' is visible in the bottom right corner of the image.

33	GX-B1488/21-F-23004~F-23005	2023. 12. 21	所检项目合格	
34	GX-B1377/22-F-23308	2023. 12. 21	所检项目合格	
35	GX-B1502/21-F-23054	2023. 12. 22	II类，自燃。	
36	GX-B1501/21-F-23054	2023. 12. 22	煤尘具有爆炸性	