

序号	报告编号	发布日期	结论	影像资料
1	GX-B1416/22-Y-23089	2024年1月2日	综合判定：合格	

2	GX-B1385/21-Y-23092	2024年1月2日	所检项目合格。	
3	GX-B1385/21-Y-23093	2024年1月2日	所检项目合格。	

4	GX-B1385/21-Y-23094	2024年1月2日	所检项目合格。	
5	GX-B1385/21-Y-23095	2024年1月2日	所检项目合格。	

6	GX-B1310/21-Y-23196	2024年1月2日	符合标准要求。	 <p>A photograph showing a worker in a white protective suit and helmet working on a blue industrial machine. The worker is wearing gloves and appears to be using a tool. The date stamp '2023/12/13' is visible in the bottom right corner of the image.</p>
7	GX-B1310/21-Y-23197	2024年1月2日	符合标准要求。	 <p>A photograph showing a worker in a camouflage uniform and helmet working on a yellow industrial machine. The worker is wearing a dark helmet and appears to be using a tool. The date stamp '2023/12/13' is visible in the bottom right corner of the image.</p>


8	GX-B1310/21-Y-23198	2024年1月2日	符合标准要求。	 A person wearing a camouflage uniform and a helmet is working on a yellow metal platform. The person is looking down at something in their hands. The background is a light blue wall. A yellow timestamp '2023/12/13' is visible in the bottom right corner of the photo.
9	GX-B1310/21-Y-23199	2024年1月2日	符合标准要求。	 A person wearing a camouflage uniform and a helmet is working on a yellow metal platform. The person is looking down at something in their hands. The background is a light blue wall. A yellow timestamp '2023/12/13' is visible in the bottom right corner of the photo.

10	GX-B1306/23-Y-23153	2024年1月3日	综合判定：合格。	
11	GX-B1306/23-Y-23154	2024年1月3日	综合判定：合格。	

12	GX-B1306/23-Y-23155	2024年1月3日	综合判定：合格。	
13	GX-B1306/23-Y-23156	2024年1月3日	综合判定：合格。	

14	GX-B1328/20-Y-23167	2024年1月2日	本次共检绝缘手套12只，12只绝缘手套合格。	 <p>A photograph showing several workers in a workshop setting. They are wearing safety gear, including red hard hats and work clothes. One worker is kneeling on the floor, working with a piece of equipment, possibly a testing device for gloves. There are various tools, a red bucket, and a wheelbarrow visible. A date stamp '2023/12/28' is visible in the bottom right corner of the image.</p>
15	GX-B1328/20-Y-23168	2024年1月2日	本次共检绝缘鞋12只，12只绝缘鞋合格。	 <p>A photograph showing workers in a workshop testing insulation shoes. A worker in a red hard hat is kneeling on the floor, working with a testing device. In the foreground, a row of black insulation shoes is laid out on the floor. A red bucket and a pink basin are also visible. A date stamp '2023/12/28' is visible in the bottom right corner of the image.</p>

16	GX-B1328/20-Y-23169	2024年1月2日	本次共检便携式接地和接地短路装置6组，6组便携式接地和接地短路装置合格。	
----	---------------------	-----------	--------------------------------------	---

17	GX-B1328/20-Y-23170	2024年1月2日	本次共检验电器 8支，8支验电器所 检项目合格。	
----	---------------------	-----------	--------------------------------	---

18	GX-B1321/20-Y-23641-23641	2024年1月2日	本次共检验电力电缆2条，2条电力电缆所检项目合格。	 <p>2023/12/25</p>
19	GX-B1328/20-Y-23642	2024年1月2日	检项目合格。	 <p>2023/12/27</p>

20	GX-B1495/20-Y-231734~ 231748	2024年1月2日	本次共检高压开关 设备15台，15台高 压开关设备所检项 目合格。	
21	GX-B1495/20-Y-231749~ 231761	2024年1月2日	本次共检高压开关 设备13台，13台高 压开关设备所检项 目合格。	

22	GX-B1495/20-Y-231762~ 231772	2024年1月2日	本次共检高压开关 设备11台，11台高 压开关设备所检项 目合格。	
----	---------------------------------	-----------	--	---

23	GX-B1495/20-Y-231773~ 231787	2024年1月2日	本次共检高压开关设备15台，15台高压开关设备所检项目合格。	 <p>2023/12/27</p>
24	GX-B1495/20-Y-231788~ 231800	2024年1月2日	本次共检高压开关设备13台，13台高压开关设备所检项目合格。	 <p>2023/12/28</p>

25	GX-B1308/23-Y-23019	2024年1月2日	综合判定：合格。	
26	GX-B1499/23-Y-23115	2024年1月2日	所检项目合格。	

27	GX-B1499/23-Y-23116	2024年1月2日	所检项目合格。	
28	GX-B1499/23-Y-23117	2024年1月2日	所检项目合格。	

29	GX-B1306/23-Y-23157	2024年1月3日	综合判定：合格。	 A worker wearing a grey uniform and a red hard hat is inspecting a piece of equipment. The worker is looking into an open compartment of a machine. A yellow timestamp '2023/12/22' is visible in the bottom right corner of the photo.
30	GX-B1306/23-Y-23158	2024年1月3日	综合判定：合格。	 A worker wearing a grey uniform and a red hard hat is using a tool on a wall. The worker is holding a long-handled tool and appears to be working on a surface. A yellow timestamp '2023/12/22' is visible in the bottom right corner of the photo.

31	GX-B1306/23-Y-23159	2024年1月3日	综合判定：合格。	 <p>2023/12/22</p>
32	GX-B1354/20-Y-23015	2024年1月4日	电网接地电容电流符合规定。	 <p>2023/12/22</p>

33	GX-B1539/22-Y-23284	2024年1月3日	所检项目合格。	
34	GX-B1539/22-Y-23285	2024年1月3日	所检项目合格。	
35	GX-B1539/22-Y-23286	2024年1月3日	所检项目合格。	

36	GX-B1539/22-Y-23287	2024年1月3日	所检项目合格。	 A yellow wheel loader is shown in an outdoor setting, possibly a construction or mining site. A person in a red jacket and white pants stands next to the loader for scale. The loader has 'L3500D' and 'L3500D' visible on its side. A yellow timestamp '2023/12/25' is in the bottom right corner of the photo.
37	GX-B1539/22-Y-23288	2024年1月3日	所检项目合格。	 A yellow wheel loader is shown in an outdoor setting. A person in a white jacket and dark pants stands next to the loader for scale. The loader has 'L3500D' visible on its side. A yellow timestamp '2023/12/25' is in the bottom right corner of the photo.
38	GX-B1539/22-Y-23289	2024年1月3日	所检项目合格。	 A yellow wheel loader is shown in an outdoor setting. A person in a white jacket and dark pants stands next to the loader for scale. The loader has 'L3500D' visible on its side. A yellow timestamp '2023/12/25' is in the bottom right corner of the photo.

39	GX-B1522/20-Y-23153	2024. 1. 3	所检项目合格。	
40	GX-B1522/20-Y-23154	2024. 1. 3	所检项目合格。	
41	GX-B1521/20-Y-23634	2024年1月3日	所检项目合格。	

42	GX-B1539/22-Y-23277	2024年1月3日	所检项目合格。	 A yellow wheel loader is parked on a dirt surface. Two workers wearing white protective suits and hard hats are standing in front of the machine. The background shows a hazy, open landscape. A yellow timestamp '2023-12-11' is visible in the bottom right corner of the photo.
43	GX-B1539/22-Y-23278	2024年1月3日	所检项目合格。	 A yellow wheel loader is parked on a dirt surface. Two workers wearing white protective suits and hard hats are standing in front of the machine. The background shows a clear blue sky and some industrial structures. A yellow timestamp '2023-12-11' is visible in the bottom right corner of the photo.
44	GX-B1539/22-Y-23279	2024年1月3日	所检项目合格。	 A yellow wheel loader is parked inside a large industrial building. Two workers wearing white protective suits and hard hats are standing in front of the machine. The background shows the interior structure of the building. A yellow timestamp '2023-12-11' is visible in the bottom right corner of the photo.

45	GX-B1557/22-Y-23050	2024. 1. 4	所检项目合格。	 A photograph of a yellow bulldozer at a construction site. A person in a light-colored uniform is standing next to the bulldozer, possibly inspecting it. The bulldozer has a red number '02' on its side. The background shows a rocky, excavated area. A yellow timestamp '2024/1/4 14:14' is visible in the bottom right corner of the photo.
----	---------------------	------------	---------	--