












序号	报告编号	发布日期	结论	影像资料
1	GX-B1451/20-1-24305~24314	2024. 5. 6	本次共检高压开关设备10台，10台高压开关设备所检项目合格。	
2	GX-B1451/20-1-24315~24322	2024. 5. 6	本次共检高压开关设备8台，8台高压开关设备所检项目合格。	
3	GX-B1307/20-1-24021	2024. 5. 6	综合判定：合格。	





4	GX-B1307/20-1-24022	2024. 5. 6	综合判定：合格。	
5	GX-B1321/20-1-24596~24608	2024. 5. 6	本次共检电力电缆13条，13条电力电缆所检项目合格	
6	GX-B1321/20-1-24609~24613	2024. 5. 6	本次共检电力电缆5条，5条电力电缆所检项目合格	
7	GX-B1321/20-1-24614~24627	2024. 5. 6	本次共检电力电缆14条，14条电力电缆所检项目合格	




8	GX-B1309/21-1-24016	2024. 5. 6	所检项目合格		
9	GX-B1500/21-1-24061	2024. 5. 6	综合判定：合格		
10	GX-B1500/21-1-24062	2024. 5. 6	综合判定：合格		
11	GX-B1500/21-1-24063	2024. 5. 6	综合判定：合格		





12	GX-B1322/21-1-24159~24164	2024. 5. 7	本次共检验电力电缆6条，6条所检项目合格	
13	GX-B1322/21-1-24165~24171	2024. 5. 7	本次共检验电力电缆7条，7条所检项目合格	
14	GX-B1548/20-1-24013	2024. 5. 8	所检项目合格	
15	GX-B1548/20-1-24014	2024. 5. 8	所检项目合格	

16	GX-B1548/20-1-24015	2024. 5. 8	所检项目合格	
17	GX-B1548/20-1-24016	2024. 5. 8	所检项目合格	
18	GX-B1321/20-1-24531~24541	2024. 5. 8	本次共检电力电缆11条，11条电力电缆所检项目合格	
19	GX-B1321/20-1-24542~24553	2024. 5. 8	本次共检电力电缆12条，12条电力电缆所检项目合格	

20	GX-B1321/20-1-24554~24562	2024. 5. 8	本次共检电力电缆9条，9条电力电缆所检项目合格	
21	GX-B1534/20-1-24012	2024. 5. 9	所检项目合格	
22	GX-B1534/20-1-24013	2024. 5. 9	所检项目合格	
23	GX-B1534/20-1-24014	2024. 5. 9	所检项目合格	

24	GX-B1534/20-1-24015	2024. 5. 9	所检项目合格	
25	GX-B1534/20-1-24016	2024. 5. 9	所检项目合格	
26	GX-B1534/20-1-24017	2024. 5. 9	所检项目合格	
27	GX-B1310/21-1-24064	2024. 5. 8	符合标准要求	

28	GX-B1428/21-1-24064	2024. 5. 8	无缺陷痕迹显示	
29	GX-B1310/21-1-24065	2024. 5. 8	符合标准要求	
30	GX-B1428/21-1-24065	2024. 5. 8	无缺陷痕迹显示	
31	GX-B1310/21-1-24059	2024. 5. 8	符合标准要求	

32	GX-B1427/21-1-24059	2024. 5. 8	无缺陷磁痕显示	
33	GX-B1310/21-1-24060	2024. 5. 8	符合标准要求	
34	GX-B1428/21-1-24060	2024. 5. 8	无缺陷迹痕显示	
35	GX-B1428/21-1-24062	2024. 5. 8	无缺陷迹痕显示	

36	GX-B1310/21-1-24063	2024. 5. 8	符合标准要求	 2024.4.29
37	GX-B1427/21-1-24063	2024. 5. 8	符合标准要求	 2024.4.29
38	GX-B1310/21-1- 24072	2024/5/9	符合标准要求	 2024/4/12

39	GX-B1310/21-1- 24073	2024/5/9	符合标准要求	 A worker wearing a white protective suit, a red helmet, and safety glasses is working on a blue metal structure. The worker is holding a tool and appears to be inspecting or adjusting a component. The background shows an industrial setting with various pipes and structures. A yellow timestamp '2024/4/12' is visible in the bottom right corner of the image.
40	GX-B1310/21-1- 24061	2024/5/9	符合标准要求	 A worker wearing an orange protective suit, a red helmet, and safety glasses is working on a white panel. The worker is holding a tool and appears to be inspecting or adjusting a component. The background is dark, suggesting an indoor industrial setting. A yellow timestamp '2024/4/24' is visible in the bottom right corner of the image.