

序号	报告编号	发布日期	结论	影像资料
1	GX-B1521/20-Y-24192	2024. 5. 1	所检项目合格。	
2	GX-B1521/20-Y-24193	2024. 5. 1	所检项目合格。	



3	GX-B1521/20-Y-24194	2024. 5. 1	所检项目合格。		
4	GX-B1521/20-Y-24195	2024. 5. 1	所检项目合格。		


5	GX-B1521/20-Y-24196	2024. 5. 1	所检项目合格。	
6	GX-B1539/22-Y-24094	2024. 5. 1	所检项目合格。	

7	GX-B1539/22-Y-24095	2024. 5. 1	所检项目合格。	
8	GX-B1521/20-Y-24166	2024年5月1日	所检项目合格	

9	GX-B1539/22-Y-24078	2024年5月6日	所检项目合格。	
10	GX-B1522/20-Y-24036	2024年5月6日	所检项目合格。	

11	GX-B1522/20-Y-24037	2024年5月6日	所检项目合格。	 <p>2024/4/19</p>
12	GX-B1522/20-Y-24038	2024年5月6日	所检项目合格。	 <p>2024/4/19</p>

13	GX-B1522/20-Y-24039	2024年5月6日	所检项目合格。	
14	GX-B1557/22-Y-24014	2024年5月6日	所检项目合格。	

15	GX-B1539/22-Y-24107	2024年5月6日	所检项目合格。	
16	GX-B1556/22-Y-24008	2024年5月6日	所检项目合格。	



17	GX-B1556/22-Y-24009	2024年5月6日	所检项目合格。	
18	GX-B1423/20-Y-24001	2024. 5. 7	综合判定：合格	

19	GX-B1423/20-Y-24002	2024. 5. 7	综合判定：合格	
20	GX-B1423/20-Y-24003	2024. 5. 7	综合判定：合格	



21	GX-B1423/20-Y-24004	2024. 5. 7	综合判定：合格	
22	GX-B1423/20-Y-24005	2024. 5. 7	综合判定：合格	



23	GX-B1539/22-Y-24072	2024年5月6日	所检项目合格。	
24	GX-B1539/22-Y-24073	2024年5月6日	所检项目合格。	



25	GX-B1521/20-Y-24169	2024年5月6日	所检项目合格。	 A photograph showing a worker wearing a red hard hat and a high-visibility yellow safety vest. The worker is seated on a piece of machinery, possibly a tractor or a similar vehicle, and is looking down at a handheld device or control panel. The background is slightly blurred, showing an outdoor setting. A yellow timestamp '2024/5/21' is visible in the bottom left corner of the image.
26	GX-B1521/20-Y-24170	2024年5月6日	所检项目合格。	 A photograph of a yellow excavator with a large bucket full of dark material, likely coal or ore. Two workers in high-visibility vests and hard hats are standing near the base of the excavator. The background shows a large pile of material under a blue sky with some clouds. A yellow timestamp '2024/4/21' is visible in the bottom right corner of the image.

27	GX-B1521/20-Y-24171	2024年5月6日	所检项目合格。	
28	GX-B1521/20-Y-24172	2024年5月6日	所检项目合格。	

29	GX-B1557/22-Y-24010	2024年5月6日	所检项目合格。	 A close-up photograph of a worker wearing a yellow safety vest and a red hard hat, operating a yellow tracked loader. The worker is inside the cab, holding a vertical rod. The machine has "Pro" written on its side and a date stamp "2024/4/22" in the bottom left corner.
30	GX-B1556/22-Y-24007	2024年5月6日	所检项目合格。	 A photograph of a worker in a yellow safety vest and red hard hat standing next to a yellow tracked loader. The loader's bucket is raised. The machine has "第二队" and "824-10" written on its side. A date stamp "2024/4/22" is visible in the bottom right corner.

31	GX-B1310/21-Y-24101	2024年5月6日	符合标准要求。	 A worker wearing a red hard hat and a blue uniform is kneeling on a dark surface, using a handheld device to inspect a white vertical surface. The date '2024/5/6' is visible in the bottom left corner of the photo.
32	GX-B1428/21-Y-24101	2024年5月6日	无缺陷迹痕显示。	 A worker is inspecting a large, curved, metallic structure, possibly a turbine or engine component. The worker is wearing a red hard hat and a blue uniform. The date '2024/5/6' is visible in the bottom left corner of the photo.

33	GX-B1310/21-Y-24102	2024年5月6日	符合标准要求。	 <p>A worker wearing a red hard hat and a dark blue uniform with reflective stripes is using a handheld electronic device. The worker is standing next to a blue vertical structure. A yellow timestamp '2024/4/21' is visible in the bottom left corner of the photo.</p>
34	GX-B1428/21-Y-24102	2024年5月6日	无缺陷迹痕显示。	 <p>A worker in a blue uniform and white hard hat is inspecting a dark, confined space. The worker is using a flashlight to illuminate the area. A yellow timestamp '2024/4/21' is visible in the bottom left corner of the photo.</p>

35	GX-B1423/20-Y-24012	2024年5月8日	综合判定：合格。	
36	GX-B1423/20-Y-24006	2024年5月8日	综合判定：合格。	

37	GX-B1423/20-Y-24007	2024年5月8日	综合判定：合格。	
38	GX-B1423/20-Y-24008	2024年5月8日	综合判定：合格。	



39	GX-B1423/20-Y-24009	2024年5月8日	综合判定：合格。	
40	GX-B1423/20-Y-24010	2024年5月8日	综合判定：合格。	

41	GX-B1423/20-Y-24011	2024年5月8日	综合判定：合格。	
42	GX-B1521/20-Y-24205	2023年5月8日	所检项目合格。	

43	GX-B1539/20-Y-24100	2023年5月8日	所检项目合格。	
44	GX-B1539/20-Y-24090	2023年5月8日	所检项目合格。	

45	GX-B1539/20-Y-24091	2023年5月8日	所检项目合格。	 A photograph showing a worker from an interior perspective, seated in the operator's seat of a vehicle. The worker is wearing a red hard hat, safety glasses, and a light blue uniform. They are holding a tool or device in their right hand. The background shows a window with a view of trees. A small timestamp '2024.4.27' is visible in the bottom right corner of the image.
46	GX-B1539/20-Y-24092	2023年5月8日	所检项目合格。	 A photograph showing a worker from an exterior perspective, seated in the operator's seat of a vehicle. The worker is wearing a red hard hat and a light blue uniform. The vehicle's door is open, and the worker is looking towards the camera. The background is a clear blue sky.

47	GX-B1539/20-Y-24093	2023年5月8日	所检项目合格。	
48	GX-B1539/20-Y-24094	2023年5月8日	所检项目合格。	

49	GX-B1521/20-Y-24189	2023年5月8日	所检项目合格。	
50	GX-B1521/20-Y-24190	2023年5月8日	所检项目合格。	

51	GX-B1521/20-Y-24191	2023年5月8日	所检项目合格。	 A close-up photograph of a worker wearing a red safety helmet and a grey uniform, focused on handling a cable or wire. The worker is wearing gloves and appears to be in a confined space. A timestamp '2024/4/27' is visible in the bottom right corner of the image.
52	GX-B1495/20-Y-241025~241028	2023年5月7日	本次共检高压开关柜4台， 4台高压开关柜所检项目合格。	 A photograph showing several workers in blue uniforms and helmets inspecting a large red high-voltage switch cabinet. The cabinet has various gauges and labels. The workers are using tools and equipment. A timestamp '2024/4/13' is visible in the bottom right corner of the image.

53	:GX-B1495/20-Y-241029~241032	2023年5月7日	本次共检高压开关柜4台， 4台高压开关柜所检项目合格。	 <p>A photograph showing several workers in dark uniforms and hard hats working in a control room or substation. They are gathered around a large piece of equipment, likely a high-voltage switchgear. A date stamp '2024/4/14' is visible in the bottom right corner of the image.</p>
54	GX-B1563/24-Y-24016	2024年5月9日	所检项目合格。	 <p>A photograph of a white and red truck, possibly a water tanker or similar utility vehicle, parked outdoors. The truck has 'MF3100' written on its side. A worker in a high-visibility vest is standing next to the truck. A date stamp '2024/4/2' is visible in the bottom right corner of the image.</p>



55	GX-B1563/24-Y-24017	2024年5月9日	所检项目合格。	
56	GX-B1563/24-Y-24018	2024年5月9日	所检项目合格。	

57	GX-B1563/24-Y-24019	2024年5月9日	所检项目合格。	
58	GX-B1563/24-Y-24020	2024年5月9日	所检项目合格。	

59	GX-B1521/20-Y-24167	2024年5月9日	所检项目合格。	 A yellow excavator is shown in a desert-like environment with its bucket raised. The machine has a blue stripe and the number '1' on its side. A person in a blue uniform is standing near the base of the excavator. The date '2024-05-09' is visible in the bottom right corner of the photo.
60	GX-B1521/20-Y-24168	2024年5月9日	所检项目合格。	 A yellow excavator is shown in a desert-like environment with its bucket lowered. The machine has a blue stripe and the number '2' on its side. A person in a blue uniform is standing near the base of the excavator. The date '2024-05-09' is visible in the bottom right corner of the photo.

61	GX-B1521/20-Y-24173	2024年5月9日	所检项目合格。	 A yellow excavator is shown in a dirt field under a clear blue sky. The excavator's arm is raised, and its bucket is open. A person in a high-visibility vest is standing near the base of the excavator. A yellow timestamp '2024/4/3' is visible in the bottom right corner of the photo.
62	GX-B1521/20-Y-24174	2024年5月9日	所检项目合格。	 A yellow excavator is shown in a dirt field under a clear blue sky. The excavator's arm is raised, and its bucket is open. Two people in high-visibility vests are standing near the base of the excavator. A yellow timestamp '2024/4/3' is visible in the bottom right corner of the photo.

63	GX-B1521/20-Y-24175	2024年5月9日	所检项目合格。	 A yellow excavator is shown at a construction site. The excavator's arm is raised, and its bucket is positioned over a pile of material. Two workers in high-visibility vests are standing near the excavator. The background shows a clear blue sky and a dirt area. A yellow timestamp '2024/4/3' is visible in the bottom right corner of the image.
64	GX-B1521/20-Y-24176	2024年5月9日	所检项目合格。	 A yellow excavator is shown at a construction site. The excavator's arm is raised, and its bucket is positioned over a pile of material. Two workers in high-visibility vests are standing near the excavator. The background shows a clear blue sky and a dirt area. A yellow timestamp '2024/4/3' is visible in the bottom right corner of the image.

65	GX-B1539/22-Y-24068	2024年5月9日	所检项目合格。	
66	GX-B1539/22-Y-24069	2024年5月9日	所检项目合格。	

67	GX-B1539/22-Y-24070	2024年5月9日	所检项目合格。	
68	GX-B1539/22-Y-24071	2024年5月9日	所检项目合格。	

69	GX-B1539/22-Y-24108	2024. 5. 9	所检项目合格。	
70	GX-B1539/22-Y-24109	2024. 5. 9	所检项目合格。	

71	GX-B1539/22-Y-24110	2024. 5. 9	所检项目合格。	
72	GX-B1539/22-Y-24111	2024. 5. 9	所检项目合格。	


73	GX-B1539/22-Y-24112	2024. 5. 9	所检项目合格。	
74	GX-B1539/22-Y-24113	2024. 5. 9	所检项目合格。	

75	GX-B1539/22-Y-24114	2024. 5. 9	所检项目合格。	
76	GX-B1539/22-Y-24115	2024. 5. 9	所检项目合格。	

77	GX-B1521/20-Y-24203	2024年5月9日	所检项目合格。	
78	GX-B1521/20-Y-24204	2024年5月9日	所检项目合格。	

79	GX-B1499/23-Y-24021	2024. 5. 9	实测流量为79. 2m ³ /h。	
80	GX-B1499/23-Y-24022	2024. 5. 9	实测流量为68. 8m ³ /h。	

81	GX-B1499/23-Y-24023	2024. 5. 9	实测流量为69. 6m ³ /h。	
82	GX-B1499/23-Y-24024	2024. 5. 9	实测流量为78. 5m ³ /h。	

83	GX-B1499/23-Y-24025	2024. 5. 9	实测流量为69. 1m ³ /h。	
84	GX-B1499/23-Y-24026	2024. 5. 9	实测流量为69. 7m ³ /h。	