

序号	报告编号	发布日期	结论	影像资料
230	GX-B1428/21-Y-24104	2024年5月16日	无缺陷迹痕显示。	 A worker in a grey uniform and red helmet is inspecting a large, dark-colored industrial component. A pink laser line is visible on the surface. The date stamp '2024/4/30' is in the bottom right corner.
231	GX-B1310/21-Y-24104	2024年5月16日	符合标准要求。	 A worker in a grey uniform and red helmet is inspecting a large, red industrial component. The worker is using a tool to inspect a specific part of the component. The date stamp '2024/4/30' is in the bottom right corner.

232	GX-B1428/21-Y-24105	2024年5月16日	无缺陷迹痕显示。	
233	GX-B1310/21-Y-24105	2024年5月16日	符合标准要求。	

234	GX-B1310/21-Y-24062	2024年5月16日	符合标准要求。	
235	GX-B1539/22-Y-24150	2024年5月17日	所检项目合格。	

236	GX-B1521/20-Y-24228	2024年5月17日	所检项目合格。	
237	GX-B1521/20-Y-24229	2024年5月17日	所检项目合格。	

238	GX-B1521/20-Y-24230	2024年5月17日	所检项目合格。	
239	GX-B1521/20-Y-24231	2024年5月17日	所检项目合格。	

240	GX-B1521/20-Y-24232	2024年5月17日	所检项目合格。	
241	GX-B1521/20-Y-24233	2024年5月17日	所检项目合格。	

242	GX-B1521/20-Y-24234	2024年5月17日	所检项目合格。	
243	GX-B1521/20-Y-24235	2024年5月17日	所检项目合格。	

244	GX-B1521/20-Y-24236	2024年5月17日	所检项目合格。	
245	GX-B1521/20-Y-24237	2024年5月17日	所检项目合格。	

246	GX-B1521/20-Y-24238	2024年5月17日	所检项目合格。	 A yellow tracked excavator is shown in a construction or mining site. The excavator is positioned on a rocky surface, and its arm is extended. Two workers in safety gear are visible near the machine. A yellow timestamp '2024/4/15' is visible in the bottom right corner of the image.
247	GX-B1521/20-Y-24239	2024年5月17日	所检项目合格。	 An orange tracked excavator is shown in a construction or mining site. The excavator is positioned on a rocky surface, and its arm is extended. Two workers in safety gear are visible near the machine. A yellow timestamp '2024/4/15' is visible in the bottom right corner of the image.

248	GX-B1521/20-Y-24240	2024年5月17日	所检项目合格。	 A photograph of a red Hitachi excavator with a large bucket, parked on a dirt surface. Two workers in safety gear are standing near the machine. A yellow timestamp '2024/4/15' is visible in the bottom right corner of the photo.
249	GX-B1521/20-Y-24241	2024年5月17日	所检项目合格。	 A photograph of a red Hitachi excavator with a large bucket, parked on a dirt surface. Two workers in safety gear are standing near the machine. A yellow timestamp '2024/4/15' is visible in the bottom right corner of the photo.

250	GX-B1521/20-Y-24242	2024年5月17日	所检项目合格。	
251	GX-B1521/20-Y-24243	2024年5月17日	所检项目合格。	

252	GX-B1521/20-Y-24244	2024年5月17日	所检项目合格。	 A photograph of a red Hitachi excavator with its bucket raised, parked on a dirt lot. A person in a blue uniform stands nearby. The date stamp '2024/4/16' is visible in the bottom right corner.
253	GX-B1521/20-Y-24245	2024年5月17日	所检项目合格。	 A photograph of a red Hitachi excavator with its bucket lowered, parked on a dirt lot. The date stamp '2024/4/16' is visible in the bottom right corner.

254	GX-B1521/20-Y-24246	2024年5月17日	所检项目合格。	
255	GX-B1521/20-Y-24247	2024年5月17日	所检项目合格。	

256	GX-B1521/20-Y-24248	2024年5月17日	所检项目合格。	
257	GX-B1521/20-Y-24249	2024年5月17日	所检项目合格。	

258	GX-B1521/20-Y-24250	2024年5月17日	所检项目合格。	
259	GX-B1521/20-Y-24251	2024年5月17日	所检项目合格。	

260	GX-B1521/20-Y-24252	2024年5月17日	所检项目合格。	 A yellow Hitachi excavator is shown in operation on a construction site. The machine is positioned on a pile of rubble and dirt. A person in a red hard hat is visible near the base of the excavator. The date stamp '2024/4/16' is visible in the bottom right corner of the image.
261	GX-B1539/22-Y-24119	2024年5月17日	所检项目合格。	 A yellow wheel loader is parked on a dirt surface. Two workers wearing red hard hats and work clothes are standing in front of the machine. The date stamp '2024/4/13' is visible in the bottom right corner of the image.

262	GX-B1539/22-Y-24120	2024年5月17日	所检项目合格。	
263	GX-B1539/22-Y-24121	2024年5月17日	所检项目合格。	

264	GX-B1539/22-Y-24122	2024年5月17日	所检项目合格。	
265	GX-B1539/22-Y-24123	2024年5月17日	所检项目合格。	

266	GX-B1539/22-Y-24124	2024年5月17日	所检项目合格。	
267	GX-B1539/22-Y-24125	2024年5月17日	所检项目合格。	


268	GX-B1539/22-Y-24126	2024年5月17日	所检项目合格。	
269	GX-B1539/22-Y-24127	2024年5月17日	所检项目合格。	

270	GX-B1539/22-Y-24128	2024年5月17日	所检项目合格。
271	GX-B1539/22-Y-24129	2024年5月17日	所检项目合格。



272	GX-B1539/22-Y-24130	2024年5月17日	所检项目合格。	
273	GX-B1521/20-Y-24261	2024年5月17日	所检项目合格。	

274	GX-B1521/20-Y-24262	2024年5月17日	所检项目合格。	
275	GX-B1328/20-Y-24033	2024. 5. 17	本次共检验电器15支， 15支验电器所检项目合格。	

276	GX-B1328/20-Y-24034	2024. 5. 17	本次共检便携式接地和接地短路装置4组，4组便携式接地和接地短路装置所检项目合格。	
277	GX-B1328/20-Y-24035	2024. 5. 17	本次共检绝缘杆8支，8支绝缘杆所检项目合格。	

278	GX-B1328/20-Y-24042	2024. 5. 17	本次共检绝缘胶垫 50块，50块绝缘胶垫合格。	
279	GX-B1495/20-Y-241179~241189	2024年5月17日	本次共检高压防爆开关 11台，11台高压防爆开关所检项目合格。	

280	GX-B1495/20-Y-241190~241194	2024年5月17日	本次共检高压防爆开关5台，5台高压防爆开关所检项目合格。	
281	GX-B1495/20-Y-241195~241202	2024年5月17日	本次共检高压防爆开关8台，8台高压防爆开关所检项目合格。	

282	GX-B1495/20-Y-241203~241207	2024年5月17日	本次共检高压防爆开关5台，5台高压防爆开关所检项目合格。	
283	GX-B1495/20-Y-241208~241215	2024年5月17日	本次共检高压防爆开关8台，8台高压防爆开关所检项目合格。	

284	GX-B1404/20-Y-24011	2024年5月20日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
285	GX-B1404/20-Y-24012	2024年5月20日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

286	GX-B1522/20-Y-24040	2023年5月17日	所检项目合格。	
287	GX-B1522/20-Y-24041	2023年5月17日	所检项目合格。	

288	GX-B1522/20-Y-24042	2023年5月17日	所检项目合格。	
289	GX-B1495/20-Y-241033~241045	2024年5月21日	本次共检高压开关设备13台，13台高压开关设备所检项目合格。	

290	GX-B1495/20-Y-241046~241064	2024年5月21日	本次共检高压开关设备19台，19台高压开关设备所检项目合格。	
291	GX-B1495/20-Y-241065~241080	2024年5月21日	本次共检高压开关设备16台，16台高压开关设备所检项目合格。	

292	GX-B1310/21-Y-24063	2024年5月20日	符合标准要求。	
293	GX-B1427/21-Y-24063	2024年5月20日	符合标准要求。	

294	GX-B1310/21-Y-24064	2024年5月20日	符合标准要求。	 <p>A photograph showing a worker in a white uniform and red helmet standing on a metal structure, possibly a ladder or scaffolding, working on a large industrial component. The structure is supported by chains and cables. The worker is positioned in the center of the frame, facing away from the camera. The background shows an outdoor industrial setting with a blue sky and some structures.</p>
295	GX-B1427/21-Y-24064	2024年5月20日	符合标准要求。	 <p>A photograph showing a worker in a white uniform and red helmet working on a large industrial structure. The worker is in the foreground, looking towards the structure. The structure is complex, with many chains and cables. The worker is positioned on the left side of the frame. The background shows an outdoor industrial setting with a blue sky and some structures.</p>

296	GX-B1310/21-Y-24065	2024年5月20日	符合标准要求。	 A worker in a white uniform and red helmet is working on a large metal pipe in a factory setting. The worker is standing on a metal ladder or scaffolding, and the pipe is being held in place by a crane or hoist. The background shows industrial equipment and a blue structure.
297	GX-B1427/21-Y-24065	2024年5月20日	符合标准要求。	 A worker in a white uniform and red helmet is working on a large metal pipe in a factory setting, viewed from behind. The worker is standing on a metal ladder or scaffolding, and the pipe is being held in place by a crane or hoist. The background shows industrial equipment and a blue structure.

298	GX-B1310/21-Y-24066	2024年5月20日	符合标准要求。	 A worker in a white uniform and red helmet is working on a large industrial machine in a factory setting. The worker is standing on a ladder and appears to be adjusting or inspecting a component of the machine. The background shows other workers and industrial equipment.
299	GX-B1427/21-Y-24066	2024年5月20日	符合标准要求。	 A worker in a white uniform and red helmet is working on a large industrial machine in a factory setting. The worker is standing on a ladder and appears to be adjusting or inspecting a component of the machine. The background shows other workers and industrial equipment.

300	GX-B1547/20-Y-24246~24249	2024. 5. 21	本次共检继电保护装置4台，4台继电保护装置所检项目合格。	
301	GX-B1495/20-Y-241216~241220	2024. 5. 21	本次共检高压交流断路器5台，5台所检项目合格。	

302	GX-B1521/20-Y-24373	2024年5月22日	所检项目合格。	 A red tracked excavator with "EMG" branding on the boom, parked on a dirt surface. Two workers in blue uniforms are standing near the machine. A yellow timestamp "2024/5/18" is visible in the bottom right corner of the photo.
303	GX-B1521/20-Y-24374	2024年5月22日	所检项目合格。	 A red tracked excavator with "EMG" branding on the boom, parked on a dirt surface. Two workers in blue uniforms are standing near the machine. A yellow timestamp "2024/5/18" is visible in the bottom right corner of the photo.

304	GX-B1556/22-Y-24011	2024年5月22日	所检项目合格。	 A yellow tracked bulldozer is parked on a dirt surface under a clear blue sky. Two workers in safety gear, one in a red vest and one in a grey uniform, stand next to the machine. A yellow timestamp '2024/5/19' is visible in the bottom right corner of the photo.
305	GX-B1321/20-Y-24218~24226	2024年5月22日	本次共检验电力电缆 9条，9条电力电缆所检 项目合格。	 A worker wearing a red hard hat and a grey uniform is kneeling on a light-colored floor, inspecting electrical equipment inside a white cabinet. A yellow timestamp '2024/5/19' is visible in the bottom right corner of the photo.

306	GX-B1321/20-Y-24357	2024年5月22日	所检项目合格。	
307	GX-B1522/20-Y-24024	2024. 5. 23	所检项目合格。	

308	GX-B1522/20-Y-24025	2024. 5. 23	所检项目合格。	
309	GX-B1522/20-Y-24026	2024. 5. 23	所检项目合格。	

310	GX-B1522/20-Y-24063	2024年5月23日	所检项目合格。	
311	GX-B1522/20-Y-24064	2024年5月23日	所检项目合格。	

312	GX-B1522/20-Y-24065	2024年5月23日	所检项目合格。	
313	GX-B1522/20-Y-24027	2024年5月23日	所检项目合格。	

314	GX-B1522/20-Y-24028	2024年5月23日	所检项目合格。	
315	GX-B1522/20-Y-24029	2024年5月23日	所检项目合格。	

316	GX-B1522/20-Y-24030	2024年5月23日	所检项目合格。	
317	GX-B1522/20-Y-24031	2024年5月23日	所检项目合格。	

318	GX-B1522/20-Y-24032	2024年5月23日	所检项目合格。	
319	GX-B1522/20-Y-24033	2024年5月23日	所检项目合格。	