

序号	报告编号	发布日期	结论	影像资料
103	GX-B1534/20-2-24067	2024. 8. 9	所检项目合格	
104	GX-B1534/20-2-24068	2024. 8. 9	所检项目合格	

105	GX-B1534/20-2-24069	2024. 8. 9	所检项目合格	
106	GX-B1534/20-2-24070	2024. 8. 9	所检项目合格	
107	GX-B1534/20-2-24071	2024. 8. 9	所检项目合格	

108	GX-B1534/20-2-24072	2024. 8. 9	所检项目合格	
109	GX-B1534/20-2-24073	2024. 8. 9	所检项目合格	
110	GX-B1534/20-2-24074	2024. 8. 9	所检项目合格	

111	GX-B1612/23-2-24007	2024/8/9	所检项目合格。	 <p>2024/07/24</p>
112	GX-B1612/23-2-24008	2024/8/9	所检项目合格。	 <p>2024/07/23</p>
113	GX-B1612/23-2-24009	2024/8/9	所检项目合格。	 <p>2024/07/23</p>

114	GX-B1612/23-2-24010	2024/8/9	所检项目合格。	
115	GX-B1495/20-2-241298~241303	2024/8/9	所检项目合格	
116	GX-B1495/20-2-241304~241310	2024/8/9	所检项目合格	


117	GX-B1495/20-2-241311~241320	2024/8/9	所检项目合格	
118	GX-B1495/20-2-241321~241332	2024/8/9	所检项目合格	
119	GX-B1495/20-2-241333~241335	2024/8/9	所检项目合格	

120	GX-B1495/20-2-241336~241344	2024/8/9	所检项目合格	 <p>2024/07/10</p>
121	GX-B1495/20-2-241345~241355	2024/8/9	所检项目合格	 <p>2024/07/10</p>
122	GX-B1495/20-2-241356~241362	2024/8/9	所检项目合格	 <p>2024/07/11</p>



123	GX-B1495/20-2-241363~241371	2024/8/9	所检项目合格	
124	GX-B1310/21-2-24255	2024. 8. 9	符合标准要求。	
125	GX-B1428/21-2-24255	2024. 8. 9	无缺陷迹痕显示。	



126	GX-B1310/21-2-24256	2024. 8. 9	符合标准要求。	
127	GX-B1428/21-2-24256	2024. 8. 9	无缺陷迹痕显示。	
128	GX-B1451/20-2-24484~24495	2024. 8. 13	所检项目合格。	

129	GX-B1495/20-2-241237	2024. 8. 13	所检项目合格。	
130	GX-B1495/20-2-241438~241441	2024. 8. 13	本次共检高压防爆开关4台，4台高压防爆开关所检项目合格。	
131	GX-B1495/20-2-241442~241449	2024. 8. 13	本次共检互感器8组，8组互感器所检项目合格。	

132	GX-B1495/20-2-241450~241452	2024. 8. 13	本次共检高压开关柜3台，3台高压开关柜所检项目合格。	 <p>2024/07/13</p>
133	GX-B1495/20-2-241453~241456	2024. 8. 13	本次共检互感器4组，4组互感器所检项目合格。	 <p>2024/07/13</p>
134	GX-B1328/20-2-24071	2024. 8. 12	所检项目合格	 <p>2024-07-04</p>

135	GX-B1328/20-2-24072	2024. 8. 12	所检项目合格	
136	GX-B1328/20-2-24074	2024. 8. 12	所检项目合格	
137	GX-B1328/20-2-24075	2024. 8. 12	所检项目合格	

138	GX-B1548/20-2-24066	2024/8/12	所检项目合格。	
139	GX-B1548/20-2-24067	2024/8/12	所检项目合格。	
140	GX-B1548/20-2-24068	2024/8/12	所检项目合格。	

141	GX-B1548/20-2-24069	2024/8/12	所检项目合格。	
142	GX-B1548/20-2-24070	2024/8/12	所检项目合格。	
143	GX-B1548/20-2-24071	2024/8/12	所检项目合格。	

144	GX-B1548/20-2-24072	2024/8/12	所检项目合格。	
145	GX-B1548/20-2-24073	2024/8/12	所检项目合格。	
146	GX-B1548/20-2-24074	2024/8/12	所检项目合格。	






147	GX-B1548/20-2-24075	2024/8/12	所检项目合格。	
148	GX-B1534/20-2-24075	2024/8/12	所检项目合格。	
149	GX-B1534/20-2-24076	2024/8/12	所检项目合格。	




150	GX-B1534/20-2-24077	2024/8/12	所检项目合格。	
151	GX-B1534/20-2-24078	2024/8/12	所检项目合格。	
152	GX-B1534/20-2-24079	2024/8/12	所检项目合格。	

153	GX-B1534/20-2-24080	2024/8/12	所检项目合格。	 A worker in a light blue uniform and a wide-brimmed hat is kneeling on the ground, inspecting the front of a yellow forklift. The forklift is parked on a paved area. In the background, there is a tall, white tower and some industrial buildings under a clear blue sky. A date stamp '2024/07/08' is visible in the bottom right corner of the photo.
154	GX-B1534/20-2-24081	2024/8/12	所检项目合格。	 Two workers in light blue uniforms and wide-brimmed hats are standing next to a yellow forklift. They appear to be inspecting the vehicle. The forklift is parked on a paved area. In the background, there is a tall, white tower and some industrial buildings under a clear blue sky. A date stamp '2024/07/08' is visible in the bottom right corner of the photo.
155	GX-B1534/20-2-24082	2024/8/12	所检项目合格。	 A worker in a light blue uniform and a red hard hat is standing next to a yellow forklift. The worker is looking at the front of the forklift. The forklift is parked on a paved area. In the background, there is a tall, white tower and some industrial buildings under a clear blue sky. A date stamp '2024/07/08' is visible in the bottom right corner of the photo.




156	GX-B1534/20-2-24083	2024/8/12	所检项目合格。	
157	GX-B1534/20-2-24084	2024/8/12	所检项目合格。	
158	GX-B1416/22-2-24019	2024. 8. 15	综合判定：合格。	

159	GX-B1416/22-2-24020	2024. 8. 15	综合判定：合格。	 <p>2024/7/29</p>
160	GX-B1416/22-2-24021	2024. 8. 15	综合判定：合格。	 <p>2024/7/30</p>
161	GX-B1416/22-2-24022	2024. 8. 15	综合判定：合格。	 <p>2024/7/30</p>

162	GX-B1598/24-2-24156	2024/8/13	实测钢丝绳有效截面积 损失百分比最大为 2.08%，小于5%为正常 。	
163	GX-B1598/24-2-24157	2024/8/13	实测钢丝绳有效截面积 损失百分比最大为 2.27%，小于5%为正常 。	
164	GX-B1598/24-2-24158	2024/8/13	实测钢丝绳有效截面积 损失百分比最大为 2.16%，小于5%为正常 。	

165	GX-B1598/24-2-24159	2024/8/13	实测钢丝绳有效截面积 损失百分比最大为 2.43%，小于5%为正常 。	
166	GX-B1598/24-2-24160	2024/8/13	实测钢丝绳有效截面积 损失百分比最大为 2.22%，小于5%为正常 。	
167	GX-B1598/24-2-24161	2024/8/13	实测钢丝绳有效截面积 损失百分比最大为 2.03%，小于5%为正常 。	





168	GX-B1598/24-2-24162	2024/8/13	实测钢丝绳有效截面积 损失百分比最大为 2.18%，小于5%为正常 。	 A photograph of a worker wearing a blue uniform, a red helmet, and safety glasses. The worker is positioned on a structure, possibly a crane or scaffolding, and is looking towards the camera. The background shows some industrial equipment. A timestamp '2024/7/14' is visible in the bottom right corner of the image.
169	GX-B1598/24-2-24163	2024/8/13	实测钢丝绳有效截面积 损失百分比最大为 1.25%，小于5%为正常 。	 A photograph showing a worker in a blue uniform and red helmet working on a structure. The worker is positioned on a platform or scaffolding, and is looking towards the camera. The background shows some industrial equipment. A timestamp '2024/7/10' is visible in the bottom right corner of the image.
170	GX-B1598/24-2-24164	2024/8/13	实测钢丝绳有效截面积 损失百分比最大为 1.17%，小于5%为正常 。	 A photograph of a worker wearing a blue uniform, a red helmet, and safety glasses. The worker is positioned on a structure, possibly a crane or scaffolding, and is looking towards the camera. The background shows some industrial equipment. A timestamp '2024/7/10' is visible in the bottom right corner of the image.

171	GX-B1310/21-2-24249	2024. 8. 13	符合标准要求。	
172	GX-B1427/21-2-24249	2024. 8. 13	符合标准要求。	
173	GX-B1310/21-2-24250	2024. 8. 13	符合标准要求。	

174	GX-B1427/21-2-24250	2024. 8. 13	符合标准要求。	
175	GX-B1310/21-2-24252	2024. 8. 13	符合标准要求。	
176	GX-B1310/21-2-24253	2024. 8. 13	符合标准要求。	

177	GX-B1310/21-2-24254	2024. 8. 13	符合标准要求。	
178	GX-B1427/21-2-24254	2024. 8. 13	符合标准要求。	
179	GX-B1534/20-2-24061	2024. 8. 14	所检项目合格。	

180	GX-B1534/20-2-24062	2024. 8. 14	所检项目合格。	
181	GX-B1534/20-2-24063	2024. 8. 14	所检项目合格。	
182	GX-B1534/20-2-24064	2024. 8. 14	所检项目合格。	