

序号	报告编号	发布日期	结论	影像资料
1	GX-B1536/20-2-24002	2024/10/9	综合判定：合格。	 A photograph showing two workers in blue and white safety gear and yellow hard hats inspecting a piece of yellow machinery in a tunnel. A date stamp '2024/08/24' is visible in the bottom right corner of the image.
2	GX-B1536/20-2-24003	2024/10/9	综合判定：合格。	 A photograph showing two workers in orange and blue safety gear and yellow hard hats inspecting a piece of yellow machinery in a tunnel. A date stamp '2024/08/24' is visible in the bottom right corner of the image.

3	GX-B1534/20-2-24129	2024/10/11	所检项目合格。	 A photograph showing a red truck parked on a paved area at a construction site. Three workers in safety gear are standing near the truck. In the background, there is a blue and white building and a green hillside. A date stamp '2024/10/14' is visible in the bottom right corner of the image.
4	GX-B1534/20-2-24130	2024/10/11	所检项目合格。	 A photograph showing a red truck parked on a paved area at a construction site. Three workers in safety gear are standing near the truck. In the background, there is a blue and white building and a green hillside. A date stamp '2024/10/14' is visible in the bottom right corner of the image.