

序号	报告编号	发布日期	结论	影像资料
21	GX-B1521/20-Y-24605	2024年10月12日	所检项目合格。	 A photograph of a yellow tracked excavator with a red bucket, parked on a dirt construction site. Two workers in high-visibility vests are standing near the machine. The date stamp in the bottom right corner reads "2024/10/11".
22	:GX-B1521/20-Y-24604	2024年10月14日	所检项目合格。	 A black and white photograph of a worker wearing a hard hat and safety vest, operating a piece of machinery. The worker is looking towards the camera. The date stamp in the bottom right corner reads "2024/10/9".

23	GX-B1539/22-Y-24313	2024年10月14日	所检项目合格。	
24	GX-B1557/22-Y-24055	2024年10月17日	所检项目合格。	

25

GX-B1556/22-Y-24028

2024年10月17日

所检项目合格。

