

序号	报告编号	发布日期	结论	影像资料
15	GX-B1539/22-Y-24347	2024年12月17日	所检项目合格。	
16	GX-B1563/24-Y-24053	2024年12月17日	所检项目合格。	

17	GX-B1559/22-Y-24035	2024年12月17日	所检项目合格。	 A photograph showing two workers in safety gear (hard hats and jackets) standing next to a large piece of machinery, possibly a forklift or similar industrial vehicle. The date stamp in the bottom right corner of the image is 2024/12/10.
18	GX-B1428/21-Y-24219	2024年12月18日	无缺陷迹痕显示。	 A photograph showing a worker in a red hard hat and dark clothing inspecting a large, dark object, possibly a piece of machinery or a component. The date stamp in the bottom right corner of the image is 2024/12/9.

19	GX-B1310/21-Y-24219	2024年12月18日	符合标准要求。	
20	GX-B1428/21-Y-24220	2024年12月18日	无缺陷迹痕显示。	

21	GX-B1310/21-Y-24220	2024年12月18日	符合标准要求。	 <p>A photograph showing a worker in a red safety helmet and dark work clothes. The worker is wearing a headlamp and is focused on a task in a dark, confined space. A blue water bottle is visible in the background. A yellow timestamp '2024/12/9' is in the bottom right corner.</p>
22	GX-B1310/21-Y-24221	2024年12月18日	符合标准要求。	 <p>A photograph of a worker wearing a bright orange protective suit with reflective stripes and a red helmet with a headlamp. The worker is holding the headlamp up towards their face. The background is dark and appears to be an industrial or underground setting. A yellow timestamp '2024/12/10' is in the bottom right corner.</p>